Enrollment:

Purchaser Name: Harjit S Jaura Phone Res:

Phone Bus:

Closing Date: July 04, 2023 Inspector: Gisella Fiore

HOMES

Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: 163B / 1B

Plan: Address: Municiaplity:

Inspection Date: June 07, 2023

Page 1 of 2 Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

## DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

## **OPERATING CONDITION**

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

KITCHEN		
COUNTERTOPS	SOAP DISPENSER NOT INSTALLED AS PER EXTRAS.	 
CABINETS	CHIP AT ISLAND GABLE FACING LIVING AT FLOOR LINE.	 
	CHIP AT UPPER RIGHT CABINET RIGHT OF HOODFAN AND FILLER RIGHT OF IT.	 
	CHIP AT UPPER RIGHT CABINET LEFT OF FRIDGE.	 
MASTER ENSUITE BATH		
FLOORING	H.O UNHAPPY WITH GROUT COLOUR AT SHOWER FLOOR- DARK TILES SELECTED SHOULD HAVE DARKER GROUT.	 
COUNTERTOPS	UPGRADED TOILET PAPER HOLDER AND TOWEL RACKS NOT INSTALLED SEE PHOTO FOR LOCATION.	 
LAUNDRY ROOM		
NOTE:	CHIP ON RIGHT SIDE SPLASH.	 
	TILE BASEBOARD NOT INSTALLED RIGHT OF DOOR	 
MAIN BATHROOM		
VANITY CABINETS	CHIP ON KICKPLATE BELOW SINK.	 
FOYER/HALL		
STAIRS	DENT ON OUTSIDE STRINGER AT STAIRS TO SECOND-FLOOR, CAN SEE FROM BASEMENT LANDING	 
	STAIN DRIP ON SECOND TRIED AT STAIRS FROM BASEMENT LANDING TWO MAIN FLOOR	 
FLOORING	AS PER HOMEOWNER UNHAPPY WITH TILES THROUGHOUT. REQUEST TO INSPECT LINES NOT	 
	EVEN.	
EXTERIOR		
PORCH	FRONT PORCH PEELING	 
	LARGE GAP BETWEEN BRICK AND SOFFIT LEFT OF FRONT DOOR	 
	CLEAN MOTOR OFF FRONT DOOR TRIM	 
NOTE:	ADJUST LENTEL AT WINDOW ABOVE GARAGE DOORS, RED SHOWING	 
	CAULKING NOT COMPLETE AT COLD SELLER ROOM VENT.	 
	DAMAGE WINDOW, MULIN LEFT OF AIR CONDITIONING UNIT	 

Enrollment:

Purchaser Name: Harjit S Jaura

Phone Res: Phone Bus:

EXTERIOR

BRICKS

Phone Bus:
Closing Date: July 04, 2023
Inspector: Gisella Fiore

UNHAPPY GAPS, VERY LARGE



Page 2 of 2

I'M INSPECT BRICKS ABOVE FRONT PORCH RIGHT SIDE BY EAVESTROUGH HOMEOWNER

Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: 163B / 1B

Plan: Address: Municiaplity:

Inspection Date: June 07, 2023

A REFERENCE FOR FUTURE WARF	ANTY REQUESTS.  o designate someone to conduct the PDI in th	HOME'S CONDITION BEFORE THE PURCHASE eir place should ensure they provide written auth	
I have inspected my new home and I	agree that the description of the items listed	on this form are accurate.	
Harjit S Jaura	Hank Jon		
Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature
		Gisella Fiore	Jan
Designate's Name (print)	Designate's Signature	Inspector's Name (print)	Inspector's Signature
Date (YYYY/MM/DD)	2023/06/07	June 07, 2023	