



	BUILDER:	Zancor Homes	JOB SITE:	Belle Aire Shores PH3		
	Customer Code:		Job Number:	18648	Board Area:8	
**	COMPLAINT DATE:	05/11/23	LOT:	189W		
	INSTALLER:		SCHEDULED DATE:	05/19/23	3	
	OWNER NAME:		OWNER TEL:			
	OWNER ADDR:		REPAIR DURATION:	0		
	ACCESS NOTES:		REPAIR TYPE:	PDI		
	REPAIRMAN:		BUILDER WO#			
	BUILDER PO#:		PO Required:	NO	Inspection Reqd:	NO
			ORIGINAL WO#:	735704		
	REPAIR DESC:	Bedroom 3 - Stretch carpet right	side of window & sea	m lifting		
		Master Bedroom - Adjust shim to				
		Bedroom 4 - Hole in floor at entra	ince to bedroom			
	PROD INFO/NOTES: PROD ORDERED:	SUPPLIER:	PO#:		DUE: / 0/	
	INSTALLER'S SIGNA	TURE:				

NOTE*** Please have this memo signed by the owner or site super upon completion.

WARNING
THINK SAFETY - ALWAYS WEAR
YOUR SAFETY SHOES AND HARDHAT



SUPER'S/OWNER'S SIGNATURE: __
















DATE: __





INSTALLER SIGNATURE





BUILDER:

Zancor Homes

JOB SITE:

Belle Aire Shores PH3

Customer Code:

Job Number:

18648 Board Area:8

COMPLAINT DATE: 05/11/23

LOT:

189W

INSTALLER:

SCHEDULED DATE: 05/19/23

OWNER NAME:

OWNER TEL:

OWNER ADDR:

REPAIR DURATION: 0

ACCESS NOTES:

REPAIR TYPE:

PDI

REPAIRMAN:

BUILDER PO#:

BUILDER WO#

PO Required:

NO

Inspection Reqd:

NO

ORIGINAL WO#:

735704

REPAIR DESC:

Bedroom 3 - Stretch carpet right side of window & seam lifting

Master Bedroom - Adjust shim to high

Bedroom 4 - Hole in floor at entrance to bedroom

PROD INFO/NOTES:

PROD ORDERED:

SUPPLIER:

PO#:

DUE: / 0/

INSTALLER'S SIGNATURE:

SUPER'S/OWNER'S SIGNATURE: _

NOTE*** Please have this memo signed by the owner or site super upon completion.

WARNING THINK SAFETY - ALWAYS WEAR YOUR SAFETY SHOES AND HARDHAT





















INSTALLER SIGNATURE

DATE