



Quality Sterling Group

Mike

REPAIR ORDER
741363



NC

BUILDER: Zancor Homes

JOB SITE: Caledon Club

Customer Code:

Job Number: 18338 Board Area:8

COMPLAINT DATE: 06/07/23

LOT: 65B

INSTALLER:

SCHEDULED DATE: 06/23/23

OWNER NAME:

OWNER TEL:

OWNER ADDR:

REPAIR DURATION: 0

ACCESS NOTES:

REPAIR TYPE: PDI

REPAIRMAN:

BUILDER WO#

BUILDER PO#:

PO Required: NO Inspection Req'd: NO

ORIGINAL WO#: 691214

REPAIR DESC:

Adjust carpet shim at entrance to all bathrooms
Master Bedroom - Tuck carpet at left side of window

PROD INFO/NOTES:

PROD ORDERED:

SUPPLIER:

PO#:

DUE: / 0/

INSTALLER'S SIGNATURE:

Michael Cole

SUPER'S/OWNER'S SIGNATURE:

[Signature]

DATE:

NOTE* Please have this memo signed by the owner or site super upon completion.**

WARNING

THINK SAFETY - ALWAYS WEAR
YOUR SAFETY SHOES AND HARDHAT



INSTALLER SIGNATURE DATE



Zancor Homes (Caledon) Ltd.
Warranty Services
Phone: (905) 738-7010
Fax: (905) 738-5948

Work Order

Closing Date: 04Jul23

Address:

Location: Caledon Club - Phase: 1B - Lot: 65B

Today's Date: 23Jun23

Contact(s):

Email:

Company: Quality Rugs Canada LTD.

Attention:

Telephone: (905) 731-4443

Fax:

Please Complete the following items:

DAI	Type	Issue	Appt. Date/Time	Notes
157948	PDI	BEDROOM #2- FLOORING~ADJUST CARPET SHIM AT ENTRANCE TO BATH FROM BOTH SIDES. AND THROUGHOUT ALL WAS WASHROOMS.		
157950	PDI	MASTER BEDROOM- FLOORING~TUCK CARPET AT LEFT SIDE OF WINDOW AND ADJUST SHIM AT ENTRANCE TO BATH.		

Date Completed: _____

Homeowner Signature: _____

The Homeowner acknowledges and accepts all work
has been completed in a workman like manner.

Date Completed: _____

Trade &/or Service Tech.

Signature: _____

Print Name: _____

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and its group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Caledon Club - Phase: 1B - Lot: 65B

157948 - 1 - FLOORING-ADJUST CARPET SHIM AT ENTRANCE TO BATH FROM BOTH SIDES. AND THROUGHOUT ALL WAS WASHROOMS.



157950 - 1 - FLOORING-TUCK CARPET AT LEFT SIDE OF WINDOW AND ADJUST SHIM AT ENTRANCE TO BATH.



157950 - 2 - FLOORING-TUCK CARPET AT LEFT SIDE OF WINDOW AND ADJUST SHIM AT ENTRANCE TO BATH.

