_1
Ψ.I
5 I
의
31
<u>@</u>
뢰
- 1

Purchaser Name: Saurabh Jain

Phone Res: Phone Bus:

Phone Bus: (647) 462-0444
Closing Date: June 26, 2023
Inspector: Alexandria Damlanidis



Vendor / Builder: Project: Lot / Phase: Plan:

24B / 1B Zancor Homes (Caledon) Ltd.

Address:

Municiapility: Inspection Date: May 29, 2023

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

Page 1 of 2

- DAMAGED, INCOMPLETE OR MISSING

 Windows, side lights and other glazing. Window and door screens
 Bathlub sinks and tollets

 Bathroom accessories if provided

 Mirrors, counter tops and cabinetry

 Flooring (hardwood, vinyl, ceramic tiles, carpeting)

 Interior (inlished and trim carpentry)

- Hot water hieater, if provided (not rental) Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
 Faucets: Kitchen, bathroom, laundry room
 Exhaust fans (kitchen, bathrooms) if provided
 Electrical outlets and fixtures
 Gast freplaces, incl.circulation fans, if provided
 Heat Recovery Vertitation system, if provided
 Heating system
 Hot water heater, if provided (not rental)
 Alt conditioning system, if provided and if conditions permit

EXTERIOR		
NOTE:	ADJUST LENTIL AT HARDY BOARD LEFT OF WINDOW LEFT OF FRONT PORCH	
	CAULKING CRACKED LEFT WINDOW	
	REMOVE METAL FROM FRONT PORCH FOUNDATION WALL	
PORCH	PORCH CHIPPED	
	REMOVE MORTAR SPLATTERS AT FRONT PORCH	
PAINT	PAINT MISSING ON FRONT DOOR	
KITCHEN		m.man.jp
CABINETS	CHIP ON LEFT UPPER SHELF BESIDE FIREPLACE	
	CHIP AT CORNER CABINET BACK GABLE	
	CHIPS AT ISLAND GABLE FACING PATIO DOOR	
WINDOWS	CHIPS AT PATIO DOOR	
MASTER ENSUITE BATH		
VANITY CABINETS	CHIPS ON BOTTOM GABLE BELOW LEFT SINK BIG CHIP ON LEFT AND RIGHT GABLE BELOW LEFT SINK SAME WITH RIGHT SINK LEFT DOOR LEFT DOOR	
MAIN BATHROOM		
VANITY CABINETS	SCRATCHES ON KICKPLATE	
UPPER HALL		
FLOORING	FLOOR SQUEAK IN UPPER HALL INFRONT OF BEDROOM 2	

Purchaser Name: Enrollment:

Saurabh Jain

Phone Res:

Phone Bus: Closing Date: (647) 462-0444 June 26, 2023

Alexandria Damianidis

ANCOR HOMES

Vendor / Builder:

Zancor Homes (Caledon) Ltd. 24B / 1B

Project: Lot / Phase: Plan:

Address:

Municiapility: inspection Date: May 29, 2023

Page 2 of 2

POWDER ROOM
SINK/FAUCET/PLUMBING STAIRS FOYER/HALL CRACK ON 1ST SPINDAL AT FIRST LANDING
CHIP ON 6TH SPINDAL FROM MAIN TO FIRST LANDING
CHIP BELOW NOSING AT STAIRS FROM MAIN TO 1ST LANDING
VARNISH MISSING ON RAILING AT FIRST LANDING FROM MAIN
DAMAGED 8TH SPINDAL ON 2ND FLOOR
VARNISH REQUIRED ON 3RD TREAD AT MAIN FLOOR
VARNISH REQUIRED ON 3RD TREAD AT MAIN FLOOR
VARNISH REQUIRED ON 3RD TREAD AT MAIN FLOOR PARTS IN STAIRS CHIP ON NOISING AT FIRST LANDING WASTER STOPPER NOT HOLDING WATER DENTED DENTED DENTED 250

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.

I have inspected my new home and I agree that the description of the items listed on this form are accurate.

Date (YYYY/MM/DD) Designate's Name (print) Purchaser's Name (print) Saurabh Jain 2023/05/29 Designate's Signature Purchaser's Signature May 29, 2023 Inspector's Name (print) Alexandria Damianidis Purchaser's Name (print) Inspector's Signature Purchaser's Signature