

Pre-Delivery Inspection (PDI) Form

LOCAL LEGENDARY LISTING®

SITE: STEELE RINT
WASATA

LOT #: 90

ENROLMENT # H

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any "substitutions" of items referred to in, or to be selected under, the Agreement of Purchase and Sale (APS).

PAGE #: 1 OF 2

Item #	Room/Location	Description
①	MSR ENSUITE	MIRROR CRACKED @ LOWER LEFT BOTTOM (PAIR) LP METRO ✓
②	KITCHEN	REQUIRE VARIANCE LEFT OF STOVE. -N1 ✓
③	2ND ENSUITE	INSPECT TUB @ LOWER LEFT SIDE -- NOTA ✓
④	BASEMENT	REPLACE DRAINER -- NOTIONAL AIR ✓
⑤	EXTERIOR	INSECT SEAL @ MSR BED FIRED GLASS ✓ LP WASATA MARK ✓
⑥	BASEMENT	CREAKLE WINDOW THIS STRESS (BACK (RIGHT OF FINANCE AREA) -- NEWLINE ✓
⑦	EXTERIOR	LAURENTE EXTERIOR PAINT -PT (CLEAN PAINT FROM FRONT DOOR GLASS) X
		5 INTERIOR
		2 EXTERIOR
		Homeowner Signature: <u>[Signature]</u>
		The Homeowner acknowledges and accepts that all initiated work has been completed in a workman like manner to their satisfaction.
		XADD - CLEAN GIVE & FILL NAIL HOLES @ ISLAND TRIM.
		- FRONT DOOR FRAMES - TOP SCRAMBLES.
		PAINT - DOOR OFF LOWER
		2ND INSIDE TP HOLEZ
		BEOD DOOR

Purchaser's signature

2023 06 13
Date (YYYY/MM/DD)

WHITE COPY - Zancor Homes

CANARY COPY - Purchaser

PINK COPY - Site

43 ADDITIONAL BOOK
VANDERBILT

ZANCOR HOMES

The items listed below were released to the homeowner(s) of

Lot # 90 Site/Phase: Shoreline Point


☒ House and Garage Door Keys

☐ Homeowner Manual (given at PDI)

☐ N/A Recycling and Green Bins

☐ N/A Other

The above items were received on this 29 day of JUNE, 2023

 Purchaser
 Purchaser