

## NEWMAR WINDOW MFG. INC. ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6 TEL (905) 672-1233 FAX (905) 672-1076 WO # W186070 Pack Slip:229951

Service Date: Jun 29, 2023

Priority:	Normal				Status:		SCHEE	ULED			RELEASI	ED
BUILDER												
Customer:	N000633				City:		WASA	GA BEACH	l F	Received	May 09, 2	023
Name:	ZANCOR W	ASAGA SING	GLES		Service Pho	ne(s):			٦	ime:	10AM - 2F	Mc
Service Fax:					Site Phone:				(	Order:	D386910-	-1
Site Fax:					Lot#:		97		F	Phase:		
RESIDENT II	NFORMATI	ON										
Home Owner N	Name: KAR	RL, HEINZ HE	CK		Ad	dress:		184 RAM	BLEWOO	DD DRIVE		
Home Phone(s	s):				Wo	ork Phor	ne(s):					
Cell Phone(s):	905-	-566-5793			En	nail(s):		karlheck2	@gmail.d	com,		
								donna.hed	ck08@gr	nail.com		
LINKED ORD	DER INFOR	MATION (	386910-	·1)								
Customer: N	1000633 ZAN	ICOR WASA	GA SING	LES			Lot #	t: 97				
Model: 6	60-03 (BLK)						Phas	se:				
SERVICE IN	STRUCTIO	NS									121	
BEDROOM-2-V LOCK BOX CO		PERATING P	ANEL GL	ASS BR	OKEN AS B	EEN SE	RVICE	60X60 H/L	RUSH	1.06	to	
PARTS REQ	UIRED								C	all		
LN Item Descri	iption		Loca	ation	Specification	1	Size		Options			Qty
91 NEWMAF	R VINYL CAS	SEMENT	B3	,	GLASS ON SASH	NLY -	24.75	X 54.75	CLR LC	WE_ARG B	K	1
Problem Descr	ription:		10	4/0	o to	50	qu					
Warranty	***	****			П	CHARG	EABLE	S	-			
_ ∕Iaterial \$						aterial \$	139	5				
abour \$						bour \$	12	0				
						O.#:						
Cause:												
Solution:												
					***************************************							
Date Comple	eted:	ul	29/	23		Approv	ved:		1	7		H1
Ti	ïme:	Boles	n		Servic	e Signat	ure:		STE	VE		



## Service Department <servicedept@newmar.com>

## Fwd: Zancor wasaga lot 97

1 message

Melissa Green <mgreen@newmar.com>

To: Service Department <servicedept@newmar.com>

Mon, May 8, 2023 at 11:38 AM

----- Forwarded message ------

From: Louie Tesoro <tesorotruck13@gmail.com>

Date: Mon, May 8, 2023 at 11:37 AM Subject: Zancor wasaga lot 97

To: Newmar <service@newmar.com>

Cc: Ted <tschlosser@newmar.com>, Tesoro <tesorowindows@bellnet.ca>

Bedroom-2-window operating panel glass broken as been service 60x60 h/l RUSH

\*\*\*\* IN ORDER TO BETTER SERVE OUR CUSTOMERS, PLEASE NOTE THAT EFFECTIVE IMMEDIATELY ALL NEW SERVICE REQUESTS ARE TO BE SENT TO servicedept@newmar.com \*\*\*\*\*if inquiring about a follow up please email me directly at mgreen@newmar.com

Thank you Melissa Green **Customer Service Coordinator** 



20230508\_112359.jpg 1570K