



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W188263

Pack Slip: 238558

Service Date: Jun 23, 2023

Priority: Normal Status: SCHEDULED RELEASED

BUILDER

Customer: 611313 City: INNISFIL Received: Jun 02, 2023
Name: ZANCOR BELLE AIRE SHORES Service Phone(s): Time:
Service Fax: Site Phone: Order: D390450-1
Site Fax: Lot#: 215W Phase: 3

RESIDENT INFORMATION

Home Owner Name: N/A Address: N/A 1687
Home Phone(s): Work Phone(s):
Cell Phone(s): Email(s):

LINKED ORDER INFORMATION (D390450-1)

Customer: 611313 ZANCOR BELLE AIRE SHORES Lot #: 215W
Model: 50-03 CANAL/WH/LOT 215W Phase: 3

SERVICE INSTRUCTIONS

DINNING ROOM FIXED PANE CRACKED, FAR RIGHT

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
32	NEWMAR VINYL CASEMENT FIXED	DIN	GLASS ONLY - FIXED	15.75 X 50.75	CLR LOWE_ARG WH	1

-Complete

Problem Description:

☐ Warranty

Material \$

Labour \$

☐ CHARGEABLES

Material \$ 77

Labour \$ 120

P.O.#:

Cause:

Solution: Replaced broken glass

Date Completed: June 23rd, 2023

Approved: [Signature]

Time:

Service Signature: [Signature]
RAY



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W188263

Pack Slip:238558

Service Date: Jun 23, 2023

Priority: Normal Status: SCHEDULED RELEASED

BUILDER

Customer: 611313 City: INNISFIL Received: Jun 02, 2023
Name: ZANCOR BELLE AIRE SHORES Service Phone(s): Time:
Service Fax: Site Phone: Order: D390450-1
Site Fax: Lot#: 215W Phase: 3

RESIDENT INFORMATION

Home Owner Name: N/A Address: N/A
Home Phone(s): Work Phone(s):
Cell Phone(s): Email(s):

LINKED ORDER INFORMATION (D390450-1)

Customer: 611313 ZANCOR BELLE AIRE SHORES Lot #: 215W
Model: 50-03 CANAL/WH/LOT 215W Phase: 3

SERVICE INSTRUCTIONS

DINNING ROOM FIXED PANE CRACKED, FAR RIGHT

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
32	NEWMAR VINYL CASEMENT FIXED	DIN	GLASS ONLY - FIXED	15.75 X 50.75	CLR LOWE_ARG WH	1

Problem Description:

☐ Warranty

Material \$

Labour \$

☐ CHARGEABLES

Material \$

Labour \$

P.O.#:

Cause:

Solution:

Date Completed:

Approved:

Time:

Service Signature:

RAY



Service Department <servicedept@newmar.com>

215w broken glass

1 message

Nathan Simas <nathan@zancorhomes.com>

Thu, Jun 1, 2023 at 8:20 AM

To: Service Department <servicedept@newmar.com>

Cc: Melissa Green <mgreen@newmar.com>, Shonnessa Facey <sfacey@newmar.com>, Carmelo <carmelo@zancorhomes.com>, Chris DiGenova <chris@zancorhomes.com>

Good morning

Dinning room fixed pane cracked, far right

Thanks,

Nathan Simas

Finishing Supervisor

Belle Aire Shores


Cell # 416-791-9862

nathan@zancorhomes.com

2 attachments



20230601_081858.jpg
2682K



pro-OgMO1Dwj.jpeg
4692K