



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W188257
Pack Slip:227161

Service Date: Jun 23, 2023

Priority: Normal Status: SCHEDULED

BUILDER

Customer: 611313 City: INNISFIL Received: Jun 02, 2023
Name: ZANCOR BELLE AIRE SHORES Service Phone(s): Time:
Service Fax: Site Phone: Order: D387519-1
Site Fax: Lot#: 81W Phase: 3

RESIDENT INFORMATION

Home Owner Name: CHRISTOPHER, J DRISCOLL Address: 1347 STEVENS ROAD
Home Phone(s): Work Phone(s):
Cell Phone(s): 416-894-0783, 647- 236-3583 Email(s): cdriscoll711@yahoo.com, tdriscollpt@yahoo.ca

LINKED ORDER INFORMATION (D387519-1)

Customer: 611313 ZANCOR BELLE AIRE SHORES Lot #: 81W
Model: 36-06 SKIPPER OP 2FL/3BD/WH Phase: 3

SERVICE INSTRUCTIONS

MASTER BEDROOM- WINDOWS-BLACK MARK AT OPERATING WINDOW RIGHT SIDE
LIVING ROOM- WINDOWS-RIPPED SCREEN - Dropped on porch

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
81	NEWMAR VINYL CASEMENT	FAM	SCREENS-REPLA	25.0625 X		1
	-Dropped off on porch		CEMENT-WINDO	51.125		
			WS			

Problem Description:

☐ Warranty

Material \$

Labour \$

☐ CHARGEABLES

Material \$

Labour \$

P.O.#:

Cause:

Solution: Dropped off screen as nobody was home

Date Completed: June 23rd, 2023

Approved:

Time:

Service Signature:

RAY



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W188257

Pack Slip:227161

Service Date: Jun 23, 2023

Priority: Normal Status: SCHEDULED

BUILDER

Customer: 611313 City: INNISFIL Received: Jun 02, 2023
Name: ZANCOR BELLE AIRE SHORES Service Phone(s):
Service Fax: Site Phone: Order: D387519-1
Site Fax: Lot#: 81W Phase: 3

RESIDENT INFORMATION

Home Owner Name: CHRISTOPHER, J DRISCOLL Address: 1347 STEVENS ROAD
Home Phone(s): Work Phone(s):
Cell Phone(s): 416-894-0783, 647- 236-3583 Email(s): cdriscoll711@yahoo.com, tdriscollpt@yahoo.ca

LINKED ORDER INFORMATION (D387519-1)

Customer: 611313 ZANCOR BELLE AIRE SHORES Lot #: 81W
Model: 36-06 SKIPPER OP 2FL/3BD/WH Phase: 3

SERVICE INSTRUCTIONS

MASTER BEDROOM- WINDOWS-BLACK MARK AT OPERATING WINDOW RIGHT SIDE
LIVING ROOM- WINDOWS-RIPPED SCREEN

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
81	NEWMAR VINYL CASEMENT	FAM	SCREENS-REPLA CEMENT-WINDO WS	25.0625 X 51.125		1

Problem Description: _____

☐ Warranty

Material \$ _____

Labour \$ _____

☐ CHARGEABLES

Material \$ _____

Labour \$ _____

P.O.#: _____

Cause: _____

Solution: _____

Date Completed: _____

Approved: _____

Time: _____

Service Signature: _____

RAY



Zancor Homes (Innisfil) Ltd.
Warranty Services
Phone: (905) 738-7010
Fax: (905) 738-5948

Work Order

Closing Date: 25May23

Address:

Location: Belle Aire Shores - Phase: 3 - Lot: 81W

Today's Date: 24May23

Contact(s):

Email:

Company: Newmar

Attention: Alex

Telephone: (905) 672-1233

Fax: (905) 672-6350

Please Complete the following items:

DAI	Type	Issue		Appt. Date/Time	Notes
157158	PDI	MASTER BEDROOM- WINDOWS~BLACK MARK AT OPERATING WINDOW RIGHT SIDE			
157164	PDI	LIVING ROOM- WINDOWS~RIPPED SCREEN			

Date Completed: _____

Homeowner Signature: _____

The Homeowner acknowledges and accepts all work
has been completed in a workman like manner.

Date Completed: _____

Trade &/or Service Tech.

Signature: _____

Print Name: _____


Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and

it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Belle Aire Shores - Phase: 3 - Lot: 81W

**157158 - 1 - WINDOWS~BLACK MARK AT
OPERATING WINDOW RIGHT SIDE**



**157158 - 2 - WINDOWS~BLACK MARK AT
OPERATING WINDOW RIGHT SIDE**



157164 - 1 - WINDOWS~RIPPED SCREEN



157164 - 2 - WINDOWS~RIPPED SCREEN

