Enrollment:

Purchaser Name: Mohammad, Asghar Mahmood

Phone Res:

Phone Bus: (416) 303-5167 Closing Date: July 13, 2023

HOMES

Vendor / Builder:

Project: Zancor Homes (Wasaga River) Ltd.

Lot / Phase: 44 / 1 Plan: Address:

Municiaplity:

Inspection Date: July 10, 2023

Inspector: Alexandria Damianidis Page 1 of 2 Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be

selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

EXTERIOR		
PORCH	REPLACE STEPS AT FRONT, PITTED	
NOTE:	REMOVE PAINT OFF GARAGE FLOOR	
FOYER/HALL		
STAIRS	VARNISH REQUIRED AT TRIM LEFT SIDE AT 1ST LANDING AND AT RISER BELOW	
	CHIP ON OUTSIDE STRINGER AT FOURTH 6TH AND SEVENTH TREAD AT STAIRS FROM LANG TO SECOND FLOOR	
	CHIP ON THIRD AND FOURTH OUTSIDE STRINGER TREAD AT STAIRS FROM MAIN FLOOR TO LANDING TO SECOND FLOOR AND SEE FROM BASEMENT STAIRS	
	CHIP AT RIGHT NEWEL POST AT EDGE AT STAIRS AT MAIN FLOOR	
FLOORING	CHIP AT 4TH HARDWOOD PLANK FROM LEFT NEWEL POST AT MAIN FLOOR BELOW STRINGER	
	CHIP ON FIFTH HARDWOOD PLAYING FROM LEFT WALL BELOW ARCH AT ENTRANCE TO MUD ROOM	
KITCHEN		
CABINETS	CHIP AT 3RD BANK OF DRAWER	
	CHIP AND BOTTOM GABLE AT CORNER CABINET LEFT OF STOVE AND SHELF	
	MISSING SHELF AT LEFT SIDE OF ISLAND CABINET	
	CHIPS ON LEFT ISLAND AND RIGHT GABLE AT FLOOR LINE AND TRIM AT RIGHT AND LEFT SIDE OF THE ISLAND GABLES WRONG PUTTY USE TO FILL HOLES	
MASTER ENSUITE BATH		
SHOWER ENCLOSURE	SCRATCH ON MARBLE JAMB	
SHARED ENSUITE		
VANITY CABINETS	CHIP INSIDE BOTTOM RIGHT GABLE BELOW RIGHT SINK.	
NOTE:	HOMEOWNER REQUESTING TO INSPECT DOOR TO SHARE BATH FOR BUBBLE.	
BEDROOM 3 ENSUITE		
FLOORING	TILE INSTALLED RIGHT OF VANITY	
SHOWER ENCLOSURE	SCRATCHES A ON MARBLE JAMB	

Enrollment:

Purchaser Name: Mohammad, Asghar Mahmood

Phone Res:

BASEMENT

Designate's Name (print)

Date (YYYY/MM/DD)

NOTE:

Phone Bus: (416) 303-5167
Closing Date: July 13, 2023
Inspector: Alexandria Damianidis

ZANCOR HOMES

Page 2 of 2

BASEMENT WINDOW SCREENS MISSING THROUGHOUT

Designate's Signature

2023/07/10

Vendor / Builder:

Project: Zancor Homes (Wasaga River) Ltd.

Inspector's Signature

Lot / Phase: 44 / 1 Plan:

Address: Municiaplity:

Inspection Date: July 10, 2023

A REFERENCE FOR FUTURE WARRAN	TY REQUESTS. esignate someone to conduct the PDI in the	E HOME'S CONDITION BEFORE THE PURCHASE neir place should ensure they provide written authors.	
I have inspected my new home and I ag	ree that the description of the items listed	on this form are accurate.	
Mohammad, Asghar Mahmood	F		
Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature

Alexandria Damianidis

Inspector's Name (print)

July 10, 2023