

Robert Cioffi

Jose e MARIA

Mo

From:  
Sent:  
To:  
Subject:


Mary Ielpo <mary@zancorhomes.com>  
Tuesday, June 20, 2023 4:40 PM  
Robert Cioffi  
Lot 93 Wasaga

July 13

705 607 8117 12-3

Here are some pictures of the kitchen valance. Homeowner is not expecting a repair. Not sure you can touch this up to make it look good.

Note all the screw holes, chips and gap to underside of the cabinet.



- DAP back of  
L. valance to close  
gap so light doesn't  
go through

✓ - Supply 1 up  
(Maple flower brown)

- Supply 1 sheet of  
fast caps (Maple flower  
Brown)

\* On screw holes \*  
behind valance

Customer Sign

gone for  
13 July, 23