

PDI	Issue
✓	KITCHEN- CABINETS~ H ON LOWER CABINET LEFT BANK OF DRAW
✓	2) SCRATCH ON BANK OF DRAW LEFT OF STOVE
✓	SHELF NOT INSTA AT CABINET RIGHT OF BANK OF DRAWER BY 2ND
✓	SINK 4) EDGE OF VALANCE ABOVE SINK LEFT OF FRIDGE CHIPPED. 5)
✓	CHIP AT SHELF AT CABINET ABOVE FRIDGE. 6) CHIP AT BOTTOM LEFT
✓	PANTRY RIGHT OF FRIDGE AT INSIDE ND TOP SHELF 'SIDE UPPER NTRY.

	PDI	KITCHEN- CABINETS~CHIP AT BOTOOM GABLE LEFT OF POT DRAWER AT ISLAND	30Jun23 /am	M
		2) CHIP AT GARBAGE DRAWER LEFT SIDE AT ISLAND. 3) CHIP AT		M
		RIGHT GABLE AND PANLE RIGHT OF GARBAGE DRAWER AT EDGE 4) SHELF		M
		NOT INSTALLED AT ISLAND CABINET FACING LIVING AREA 5) CHIP / SCRATCH AT		M
		BOTTOM RIGHT AND LEFT CABINET AT ISLAND FACING LIVING AREA 6)		M
		CHIP AT GABLE RIGHT SIDE INFRONT OF DW 7)		M
		CHIP AT UPPER LEFT CABINET RIGHT OF WINDOW.		M
		8) CHIP AT VALANCE AT BELOW UPPER CABINET LEFT OFF HOOD FAN.		M
157025	PDI	✓ KITCHEN- CABINETS~END CABINET RIGHT OF FRIDGE SHOULD BE BROOM CLOSET.	30Jun23 /am	M
157026	PDI	LIVING ROOM- NOTE:~CHIP AT BOTTOM LEFT BUILT LEFT OF TV 2)	30Jun23 /am	