Enrollment:

Purchaser Name: Jaswinder Singh Brar

Phone Res: (647) 980-9786
Phone Bus: (416) 471-8530
Closing Date: July 31, 2023
Inspector: Gisella Fiore



Page 1 of 2

Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: 59B / 1B

Plan: Address: Municiaplity:

Inspection Date: July 21, 2023

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

MASTER ENSUITE BATH			
VANITY CABINETS	CHIP AT BOTTOM LEFT CABINET BELOW LEFT SINK AT EDGE	 	
FLOORING	REMOVE STAIN OFF TILE AT ENTRANCE TON BATH AND STAINS ON GROUT	 	
FAUCETS/PLUMBING	UPGRADED BATH ACCESSORIES NOT SUPPLIED OR INSTALLED THROUGHOUT. SEE PICTURES FOR LOCATIONS	 	
MASTER BEDROOM	10112001110110		
FLOORING	TUCK CARPET IN CLOSET RIGHT SIDE - LIFTING	 	
SHARED ENSUITE			
COUNTERTOPS	CHIPPED COUNTER TOP	 	
SHOWER ENCLOSURE	INSPECT TILES FOR CHIPS/DIRT	 	
LAUNDRY ROOM			
NOTE:	CHIPS AT BOTTOM GABLE BELOW SINK	 	
	CHIP AT LEFT SIDE OF COUNTER TOP	 	
FOYER/HALL			
STAIRS	SAW CUT AT INSIDE STRINGER AT 5TH TREAD AT STAIRS TO 2ND FLOOR	 	
	CRACK ON VANER STRIP RIGHT SIDE STAIRS TO BSMT	 	
FLOORING	GROUT REQUIRED AT CLOSET RIGHT SIDE	 	
	RAISE HARDWOOD PLANK BY NEWEL POST AT STAIRS TO BSMT	 	
NOTE:	DOOR STOP NOT INSTALLED AT FRONT DOOR	 _	
DINING ROOM			
FLOORING	CHIP ON FIRST HARDWOOD PLANK LEFT OF ENTER TO CLOSET AND FILL NAIL HOLES	 	

Enrollment:

Purchaser Name: Jaswinder Singh Brar

 Phone Res:
 (647) 980-9786

 Phone Bus:
 (416) 471-8530

 Closing Date:
 July 31, 2023

 Inspector:
 Gisella Fiore



Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: 59B / 1B

Plan: Address: Municiaplity:

Page 2 of 2 Inspection Date: July 21, 2023

KITCHEN		
CABINETS	INSPECT UPPER RIGHT AND LEFT CABINET ABOVE MICROWAVE CUT OUT AS CABINETS ARE	
	CURVED	
	SCRATCH ON UPPER RIGHT POT DRAWER RIGHT OF COOK TOP AT TOP EDGE	
	CHIP ON TOP POT DRAWER ABOVE COOK TOP	
	CHIP ON 2ND BANK OF DRAWER AND 4TH INSIDE AT GABLE	
	CHIP AT UPPER GABLE RIGHT SIDE CABINET RIGHT CORNER	
	CHIP ON LEFT ISLAND GABLE TRIM BY SLIDING DOOR	
	CHIP ON LEFT CABINET BELOW SINK	
WINDOWS	RIPPED SCREEN AT SLIDING DOOR	
EXTERIOR		
PORCH	SAW MARKS ON FRONT PORCH	
	TARP ON RIGHT SIDE OF HOUSE, TORN	
NOTE:	CAULKING BETWEEN REAR PATIO DOOR	

A REFERENCE FOR FUTURE WARRA	ANTY REQUESTS. designate someone to conduct the PDI in th	HOME'S CONDITION BEFORE THE PURCHASE eir place should ensure they provide written auth	
I have inspected my new home and I a	agree that the description of the items listed of	on this form are accurate.	
Jaswinder Singh Brar	Bikum Brur		
Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature
		Gisella Fiore	GF.
Designate's Name (print)	Designate's Signature	Inspector's Name (print)	Inspector's Signature
Date (YYYY/MM/DD)	2023/07/21	July 21, 2023	