

Outstanding Deficiencies
Shoreline Point - Phase: 1 - Lot: 90

Date Reported	Type	Number	Deficiency Description	Trade Assigned	Add Trade	Appointment Date	Item Completed	Initial
13Jun23	PDI	2	Kitchen- General- require valance left of stove	New Image Kitchens 158066	Add	21Jul23	✓	BS
13Jun23	PDI	3	Bedroom 2 Ensuite- General- inspect tub at lower left side	Nota Plumbing & Heating Inc. 158067	Add	21Jul23		
13Jun23	PDI	6	Basement- General- operable window has stress crack - right of furnace area	Newmar 158070	Add	21Jul23		
14Jun23	Interval	1	Kitchen- General- Island-Clean glue from right trim and fill nail holes at both island trims	New Image Kitchens 158079	Add	21Jul23		
30Jun23	Interval	2	Exterior- General- front door frames--touch up paint	Wasaga Zancor Warranty Service 158617	Add	21Jul23	✓	BS
07Jul23	Interval	4	Exterior- General- svc to do water test due to leak	Wasaga Zancor Warranty Service 158879	Add	21Jul23	REVIEW TO HOMEWORK	

Homeowner Signature: 

The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction.

Date: 21 July 21/23

Zancor Service Technician: 