



Quality Sterling Group

REPAIR ORDER
739431



NC

BUILDER: Zancor Homes

JOB SITE: Belle Aire Shores PH3

Customer Code:

Job Number: 18648 Board Area:8

COMPLAINT DATE: 05/17/23

LOT: 55W

INSTALLER:

SCHEDULED DATE: 05/25/23

OWNER NAME:

OWNER TEL:

OWNER ADDR:

REPAIR DURATION: 0

ACCESS NOTES:

REPAIR TYPE: E-MAIL

REPAIRMAN:

BUILDER WO#

BUILDER PO#:

PO Required: NO Inspection Req'd: NO

ORIGINAL WO#: 735697

REPAIR DESC: Basement - Adjust carpet at landing to basement above hardwood wavy
Basement - Tuck carpet by baseboard at entrance to bedroom to right side
Bedroom 5 - Adjust carpet shim throughout at entrance to all bathrooms
Master Bedroom - Inspect seam at carpet in floor
Master Bedroom - Replace 3 foot by 3 foot area of underpad due to leak

PROD INFO/NOTES:

PROD ORDERED:


SUPPLIER:

PO#:

DUE: / 0/

ROOM/AREA DETAILS:

Room Name	Area Name	PKey	Description	Underpad	Size	Notes
			21064 Opening Night/TXP140 - 3	Supreme Elite00		3 foot x 3 foot

INSTALLER'S SIGNATURE: 

SUPER'S/OWNER'S SIGNATURE: 

DATE: 6/23/23

NOTE* Please have this memo signed by the owner or site super upon completion.**

WARNING

THINK SAFETY - ALWAYS WEAR
YOUR SAFETY SHOES AND HARDHAT



HEAD PROTECTION



EYE PROTECTION



CLASS A
Compressed Gas



CLASS B
Flammable and combustible material



CLASS C
Oxidizing material



CLASS D
Corrosive material



CLASS D
Toxic material



CLASS D
Infectious material



CLASS E
Corrosive material



CLASS F
Reactive material

INSTALLER SIGNATURE

DATE



Quality Sterling Group

REPAIR ORDER
739431



NC

BUILDER: Zancor Homes

JOB SITE: Belle Aire Shores PH3

Customer Code:

Job Number: 18648 Board Area:8

COMPLAINT DATE: 05/17/23

LOT: 55W

INSTALLER:

SCHEDULED DATE: 05/25/23

OWNER NAME:

OWNER TEL:

OWNER ADDR:

REPAIR DURATION: 0

ACCESS NOTES:

REPAIR TYPE: E-MAIL

REPAIRMAN:

BUILDER WO#

BUILDER PO#:

PO Required: NO Inspection Req'd: NO

ORIGINAL WO#: 735697

REPAIR DESC: Basement - Adjust carpet at landing to basement above hardwood wavy
Basement - Tuck carpet by baseboard at entrance to bedroom to right side
Bedroom 5 - Adjust carpet shim throughout at entrance to all bathrooms
Master Bedroom - Inspect seam at carpet in floor
Master Bedroom - Replace 3 foot by 3 foot area of underpad due to leak

PROD INFO/NOTES:

PROD ORDERED:

SUPPLIER:

PO#:

DUE: / 0/

ROOM/AREA DETAILS:

Room Name	Area Name	PKey	Description
			21064 Opening Nigh/TXP140 - 3

Underpad	Size	Notes
Supreme Elite00		3 foot x 3 foot

INSTALLER'S SIGNATURE: L. R. [Signature]

SUPER'S/OWNER'S SIGNATURE: _____

DATE: 6/23/23

NOTE* Please have this memo signed by the owner or site super upon completion.**

WARNING

THINK SAFETY - ALWAYS WEAR
YOUR SAFETY SHOES AND HARDHAT



PROTECT
PROTECTION



PROTECT
PROTECTION



CLASS A
Compressed
Gas



CLASS B
Flammable and
combustible
material



CLASS C
Oxidizing
material



CLASS D
Material causing
immediate and
serious toxic
effects



CLASS D
Material causing
other toxic effects



CLASS D
Radioactive



CLASS E
Corrosive



CLASS F
Extremely
Flammable

INSTALLER SIGNATURE

DATE