

REPRINT 1

RIIII DER:	Zancor Homes	

JOB SITE:

Belle Aire Shores PH3

Customer Code:

Job Number:

18648 Board Area:8

COMPLAINT DATE: 05/24/23

LOT:

60W

INSTALLER:

GERRY

SCHEDULED DATE: 07/07/23

OWNER NAME:

OWNER TEL:

OWNER ADDR:

REPAIR DURATION: 0

ACCESS NOTES:

REPAIR TYPE:

PDI

REPAIRMAN:

Gerry

BUILDER WO#

BUILDER PO#:

PO Required:

NO

Inspection Reqd:

NO

ORIGINAL WO#:

735689

REPAIR DESC:

Bedroom 3 - Carpet short right of closet

Adjust capret shim at both entrances to bedroom Adjust carpet shims throuh whole second floor

Master bedroom - tuckcarpet at entrance to closet

tuck carpet at entrence to bedroom

carpet seam very visible

PROD INFO/NOTES:

PROD ORDERED:

SUPPLIER:

PO#:

DUE: / 0/

INSTALLER'S SIGNATURE:

SUPER'S/OWNER'S SIGNATURE: _

DATE:

NOTE*** Please have this memo signed by the owner or site super upon completion.

WARNING THINK SAFETY - ALWAYS WEAR YOUR SAFETY SHOES AND HARDHAT





















INSTALLER SIGNATURE







REPRINT 1

BUILDER:

Zancor Homes

JOB SITE:

Belle Aire Shores PH3

Customer Code:

Job Number:

18648

Board Area:8

COMPLAINT DATE: 05/24/23

LOT:

60W

INSTALLER:

GERRY

SCHEDULED DATE: 07/07/23

OWNER NAME:

OWNER TEL:

OWNER ADDR:

REPAIR DURATION: 0

ACCESS NOTES:

REPAIR TYPE:

PDI

REPAIRMAN:

Gerry

BUILDER WO#

Inspection Reqd:

NO

BUILDER PO#:

PO Required:

NO

ORIGINAL WO#:

735689

REPAIR DESC:

Bedroom 3 - Carpet short right of closet

Adjust capret shim at both entrances to bedroom Adjust carpet shims throuh whole second floor Master bedroom - tuckcarpet at entrance to closet

tuck carpet at entrence to bedroom

carpet seam very visible

PROD INFO/NOTES:

PROD ORDERED:

SUPPLIER:

PO#:

DUE: / 0/

INSTALLER'S SIGNATURE:

SUPER'S/OWNER'S SIGNATURE

DATE:

NOTE*** Please have this memo signed by the owner or site super upon completion.

WARNING





















INSTALLER SIGNATURE