Enrollment:

Purchaser Name: Amardeep, Singh Atwal

Baljeet, Kaur Atwal

Phone Res:

Phone Bus: (647) 638-8692 **Closing Date:** August 03, 2023

ZANCOR HOMES PDI Vendor / Builder: 44528

Project: Zancor Homes (Innisfil) Ltd.

Lot / Phase: 84W / 3

Plan: Address:

Municiaplity:

Inspector: Gisella Fiore Page 1 of 2 Inspection Date: July 27, 2023

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be

selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

MAIN BATHROOM		•	•
FLOORING	ADJUST CARPET SHIM AT ENTRANCE TO MAIN BATH		
FAUCETS/PLUMBING	WHISTLING AT SHOWER HEAD		
LAUNDRY ROOM			
FLOORING	ADJUST CARPET SHIM AT ENTRANCE TO LAUNDRY ROOM		
	TILE BASEBOARD NOT INSTALLED ON BOTH SIDES AND TOUCH UP GROUT		
FOYER/HALL			
CLOSET	WIRED SHELVING NOT INSTALLED AT LINEN		
STAIRS	HOLE IN TRIM BELOW NOISING AT 2ND FLOOR, CAN SEE FROM SIDE OF STAIRS		
	CHIP ON NOSING AT LANDING TO MUDROOM.		
FLOORING	INSPECT TILE INSIDE CLOSET AT MUDROOM CAN SEE BASEMENT BELOW		
NOTE:	DENTS ON MAN DOOR		
LIVING ROOM			
WINDOWS	SCREEN NOT INSTALLED		
KITCHEN			
FLOORING	HEAT REGISTER NOT FITTING IN TILE - TILE TO BE CUT		
CABINETS	SCRATCH ON BOTH PANELS AT ISLAND FACING LIVING AREA BY ELECTRICAL		
	CHIP ON UPPER RIGHT CABINET LEFT OF CORNER FILLER		
	CHIP ON RIGHT AND LEFT CABINET AT ISLAND FACING BREAKFAST AREA AND FAR LEFT		
	CABINET		
	CHIP ON RIGHT AND LEFT GABLE AT FLOOR LINE AT ISLAND		
	CHIPS ON UPPER CABINET LEFT OF HOOD FAN		
Note			
-	REMOVE PLASTER OFF FLOOR SLAB INSIDE GARAGE.		

Enrollment:

Purchaser Name: Amardeep, Singh Atwal

Baljeet, Kaur Atwal

HARD TO OPEN AND CLOSE

Phone Res:

BASEMENT

NOTE:

Phone Bus: (647) 638-8692
Closing Date: August 03, 2023
Inspector: Gisella Fiore



Page 2 of 2

BASEMENT WINDOW SCREENS NOT INSTALLED THROUGHOUT AND ADJUST BSMT WINDOWS,

Vendor / Builder: 44528

Project: Zancor Homes (Innisfil) Ltd.

Lot / Phase: 84W / 3 Plan:

Address: Municiaplity:

Inspection Date: July 27, 2023

ADO	1031 DOOR TO BASEMENT CANNOT CLOSE	L.		
A REFERENCE FOR FUTURE WARRA	ANTY REQUESTS. designate someone to conduct the PDI in the	HOME'S CONDITION BEFORE THE PURCHASE eir place should ensure they provide written author		S
I have inspected my new home and I	agree that the description of the items listed o	on this form are accurate.		
Amardeep, Singh Atwal	And V	Baljeet, Kaur Atwal		
Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature	
		Gisella Fiore	GF	
Designate's Name (print)	Designate's Signature	Inspector's Name (print)	Inspector's Signature	
Date (YYYY/MM/DD)	2023/07/27	July 27, 2023		