

The items listed below were released to the homeowner(s) of

Purchaser	Rocata & W	The above items were received on this $\mathcal{Z}^{\mathcal{K}}$ day of	N/A_ Other	N/A Recycling and Green Bins	Homeowner Manual	√ House and Garage Door Keys	Lot # 53v Site/P
Purchaser		of July , 2022					Site/Phase: BELLE AIRE SHORES .

Outstanding Deficiencies Belle Aire Shores - Phase: 3 - Lot: 53W

<u>20Jul23</u>	20Jul23	20Jul23	<u>20Jul23</u>	20Jul23	20Jul23	<u>20Jul23</u>	<u>20Jul23</u>	20Jul23	20Jul23	<u>20Jul23</u>	<u>20Jul23</u>	20Jul23	20Jul23	04Jul23	Date Reported
PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	Interval	Туре
15	14	}d CC	12	11	9	00	7	6	O.	4	ω	2	i i	-	Number
KITCHEN- CABINETS-CHIP INSIDE BOTTOM GARBAGE PULL OUT AND RIGHT AND LEFT CABINET BELOW SINK	KITCHEN- CABINETS~CHIP AT UPPER VALANCE, LEFT THE FRIDGE AT CORNER	KITCHEN- CABINETS-CHIP ON UPPER RIGHT CABINET RIGHT OF HOOD FAN AT BOTTOM RIGHT CORNER	KITCHEN- CABINETS-MULTIPLE CABINETS THROUGHOUT NOT SOFT CLOSE. (UPPER RIGHT CABINET RIGHT OF HOODFAN, ALL CABINETS AT ISLAND, UPPER LEFT CABINET LEFT OF HOODFAN.).	KITCHEN- CABINETS~CHIP ON FIRST PULL OUT POT DRAWER BELOW COOKTOP.	KITCHEN- COUNTERTOPS~SOAP DISPENSER NOT INSTALLED AT ISLAND INSTALL 6 INCHES RIGHT OF FAUCET	KITCHEN- SINK/FAUCET/PLUMBING~BOTTOM SINK GRID AS PER EXTRAS NOT INSTALLED.	MASTER ENSUITE BATH- VANITY CABINETS-CHIP AT BOTTOM RIGHT RIGHT CABINET BELOW RIGHT SINK AND RIGHT GABLE EDGE	MASTER ENSUITE BATH- VANITY CABINETS~CHIP AT 2,4 BANK OF DRAWER	MASTER ENSUITE BATH- VANITY CABINETS-CHIP AT BOTTOM LEFT CABINET LEFT OF SINK.	MASTER ENSUITE BATH- FAUCETS/PLUMBING~SHOWER HEAD NOT INSTALLEDD.	MASTER ENSUITE BATH- FLOORING~INSPECT WALL TILE IN SHOWER WHERE SHOWER HEAD WAS MOVDED - TILES RAISED.	UPPER HALL- WALLS~LINE IN STIPPLE ABOVE STAIRS.	BEDROOM #2- WALLS~RIPPLE AT CORNER LEFT SIDE AT HIGH CEILING.	Exterior- General- ready for window and door caulking	Number Deficiency Description
New Image Kitchens 159683	New Image Kitchens 159682	New Image Kitchens 159681	<u>New Image</u> <u>Kitchens</u> 159680 ₩	New Image Kitchens 159679	Redstone Marble 159677	Icon Plumbing & Heating 159676	New Image Kitchens 159675	New Image Kitchens ** 159674	New Image Kitchens ** 159673	Icon Plumbing & Heating 159672	<u>AV Classic</u> 159671	Foremont Drywall 159670	Foremont Drywall	CJ Caulking 158683	Trade Assigned
Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add Trade
NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NS	Appointment Date
														<	Item Completed
					XAL									PHI	Initial

20Jul23	20Jul23 20Jul23		20Jul23	<u>20Jul23</u>	20Jul23	20Jul23	
PDI	PDI	PDI	PDI	PDI	PDI	PDI	
23	22	21	20	19	18	17	
EXTERIOR- NOTE:~REMOVE PLASTER OFF GARAGE FLOOR SLAB	EXTERIOR- NOTE:~SECURE PLUG AT FRONT DOOR.	EXTERIOR- NOTE:~CHIP AT 17 PRECAST AND SIDE EDGE.	EXTERIOR- NOTE:~EXPOSED HOLE LEFT OF STAIRS.	EXTERIOR- NOTE;~REMOVED BLACK MARKS OFF STONE RIGHT OF PORCH	EXTERIOR- NOTE;~COLD ROOM VENTS NOT INSTALLED	EXTERIOR- SHINGLES~TORN SHINGLES AT ROOF ABOVE LEFT GARAGE PEAK. CAN SEE FROM WINDOW INSIDE.	
Foremont Drywall 159687	River Valley Masonry Group LTD 159686 Foremont Drywall		River Valley Masonry Group LTD 159726	River Valley Masonry Group LTD 159725	Zancor Construction/Labour Innisfil 159724	Trudel & Sons Roofing LTD, 159685	
Add	Add Add		Add	Add	Add	Add	
NoAppoint.	NoAppoint.		NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	
	<			<	<		
	*		RAN	P.J. V	R.AL		

Homeowner Signature:	

The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction.

Date:

Zancor Service Technician: