Enrollment:

Purchaser Name: Tarlochan, Singh Sidhu

Phone Res:

Phone Bus: (416) 889-2200
Closing Date: August 31, 2023
Inspector: Gisella Fiore

ANCOR HOMES

Page 1 of 2

selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: 156B / 1B

Plan: Address: Municiaplity:

Inspection Date: July 28, 2023

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

MASTER ENSUITE BATH		
FLOORING	LARGE CHIP AT TILE AT ENTRY TO BATH.	
FAUCETS/PLUMBING	HOT AND COLD AT SHOWER REVERED	
MASTER BEDROOM		
WINDOWS	ADJUST OPERATING WINDOW.	
BEDROOM #3		
FLOORING	CRACKED HARDWOOD PLANK AT UPPER HALL ENTRANCE TO BED #3. 1ST PLANK.	
LAUNDRY ROOM		
CABINETS	CHIP GABLE AT CABINET BELOW SINK INSIDE.	
FLOORING	MISSING TILE BASEBOARD RIGHT OF CABINET.	
BEDROOM 4 ENSUITE		
COUNTERTOPS	CHIP ON RIGHT SIDE EDGE OF COUNTERTOP.	
FOYER/HALL		
STAIRS	TAPE MARKS ON EDGES OF STAIRS WHERE CARDBOARD WAS PLACE- STAIN REQUIRED.	
	SMALL CHIP ON NEWEL AT LANDING TO 2ND FLOOR RIGHT SIDE.	
	CHIP ON LEFT NEWEL POST AT MAIN FLOOR STAIRS TO 2ND FLOOR.	
	FILL GAP AT NEWEL AND STRINGER AT LANDING RIGHT SIDE ROUGH	
	FILL CORNER RIGHT SIDE TREAD AT 2ND. TO 2ND FLOOR.	
	CHIP AT HARDWOOD PLANK BY NOSING ATSTAIRS TO BASEMENT.	
	H.O REQUEST NEWEL POST AT STAIRS TO 2ND FLOOR BE MORE FLUSH WITH FLOOR LIKE	
	BASEMENT.	
	DAMAGED NOSING LEFT SIDE AT STAIRS TO BASEMENT.	
KITCHEN		
CABINETS	CHIP INSIDE UPPER RIGHT CABINET ABOVE FRIDGE.	
FLOORING	RAISED METAL T MOLD RIGHT SIDE AT TILE.	

Enrollment:

Purchaser Name: Tarlochan, Singh Sidhu

Phone Res:

POWDER ROOM

Phone Bus: (416) 889-2200
Closing Date: August 31, 2023
Inspector: Gisella Fiore

ZANCOR HOMES

Page 2 of 2

Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: 156B / 1B

Plan: Address: Municiaplity:

Inspection Date: July 28, 2023

SINK/FAUCET/PLUMBING	SCRATCHES INSIDE SINK.		
SINK/FAUGE I/FLUIVIBING	SUNATURES INSIDE SINK.		
	TOILET SLANTED.		
	TOILET SLAINTED.		

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.

I have inspected my new home and I agree that the description of the items listed on this form are accurate.

Tarlochan, Singh Sidhu

Purchaser's Name (print) Purchaser's Signature

Purchaser's Name (print)

Purchaser's Signature

Designate's Name (print)

Designate's Signature

Inspector's Name (print)

Inspector's Signature

Date (YYYY/MM/DD)

2023/07/28

July 28, 2023

Gisella Fiore