



Quality Sterling Group

*** PREVIEW USE ONLY *** REPAIR ORDER

744835



NC

BUILDER: Zancor Homes

JOB SITE: Caledon Club

Customer Code:

Job Number: 18338 Board Area:8

COMPLAINT DATE: 07/13/23

LOT: 101B

INSTALLER:

SCHEDULED DATE: 07/31/23

OWNER NAME:

OWNER TEL: (647) 643-1043

OWNER ADDR: 112 Camino Real Drive 112
Camino Real Drive

REPAIR DURATION: 0

REPAIR TYPE: PDI

ACCESS NOTES:

BUILDER WO#

REPAIRMAN:

PO Required: NO Inspection Req'd: NO

BUILDER PO#:

ORIGINAL WO#: 691213

REPAIR DESC: Bedroom 3 - Adjust carpet shims at entrance to bath and closet left side

Bedroom 2 - Adjust carpet shims both entrances

Master Bedroom - Adjust carpet shim at entrance to master and at bathroom

PROD INFO/NOTES:

PROD ORDERED:

SUPPLIER:

PO#:

DUE: / 0/

INSTALLER'S SIGNATURE: _____

SUPER'S/OWNER'S SIGNATURE: _____

DATE: _____

NOTE* Please have this memo signed by the owner or site super upon completion.**

WARNING
THINK SAFETY - ALWAYS WEAR
YOUR SAFETY SHOES AND HARDHAT



HEAD
PROTECTION



FOOT
PROTECTION



CLASS A
Compressed
Gas



CLASS B
Flammable and
combustible
material



CLASS C
Oxidizing
material



CLASS D
Materials causing
immediate and
serious toxic
effects



CLASS D
Materials causing
other toxic effects



CLASS D
Bio hazardous
Infectious Material



CLASS E
Corrosive
Material



CLASS F
Dangerously
Reactive
Material

INSTALLER SIGNATURE

DATE