



Quality Sterling Group

MINE

REPAIR ORDER
745224



NC

BUILDER: Zancor Homes

JOB SITE: Caledon Club

Customer Code:

Job Number: 18338 Board Area:8

COMPLAINT DATE: 07/26/23

LOT: 50B

INSTALLER:

SCHEDULED DATE: 08/15/23

OWNER NAME:

OWNER TEL:

OWNER ADDR:

REPAIR DURATION: 0

ACCESS NOTES:

REPAIR TYPE: E-MAIL

REPAIRMAN:

BUILDER WO#

BUILDER PO#:

PO Required:

NO

Inspection Reqd:

NO

ORIGINAL WO#: 704732

REPAIR DESC:

Bedroom 2 - Debris under carpet

Master Bedroom - Adjust shims at entrance to bathroom

PROD INFO/NOTES:

PROD ORDERED:

SUPPLIER:

PO#:

DUE: / 0/

INSTALLER'S SIGNATURE: _____

SUPER'S/OWNER'S SIGNATURE: _____

DATE: _____

NOTE* Please have this memo signed by the owner or site super upon completion.**

WARNING

THINK SAFETY - ALWAYS WEAR
YOUR SAFETY SHOES AND HARDHAT

INSTALLER SIGNATURE

DATE

