

Closing Date: 15Jun23

Address:

Location:

Caledon Club - Phase: 1B - Lot: 38B

Today's Date:

03Aug23

Contact(s):

Anshul Jain - Cell: (647) 671-4295 - (seeanshul@gmail.com)

Vishwanath Ramagundam - Cell: (647) 671-4275 - (vishwanath@hotmail.com)

Email:

seeanshul@gmail.com

Company:

Zancor-Caledon

Attention:

Telephone:

Fax:

Please Complete the following items:

DAI	Type	Issue	Appt. Date/Time	Notes
160255	Interval	Master Ensuite- General- S/V/C to caulk corner below marble surround at shower	16Aug23 /am	DONE
160256	Interval	Laundry Room- General- caulking required at tile baseboard by door	16Aug23 /am	DONE
160257	Interval	Master Ensuite- General- water damage at trim and door trim	16Aug23 /am	REPLACEMENT REQ'D.
160258	Interval	Master Ensuite- General- svc to cut hole in ceiling and inspect water damage behind, bring thermal camera. - main floor, first floor to master, laundry room and master	16Aug23 /am	Cut 2 HOLES. ALL LOOKS TO BE DRY NO MORE

Date Completed: 17 Aug 2023

Homeowner Signature:



160257 - pending, 160258 - pending

 P. Hoare