Enrollment:

Purchaser Name:

Sandeep Arora

Phone Res:

Phone Bus: (437) 533-2001 Closing Date: September 14, 2023 Inspector: Alexandria Damianidis

Page 1 of 3

Vendor / Builder: 44528

Project: Zancor Homes (Innisfil) Ltd.

Lot / Phase: 354W / 3

Plan: Address: Municiaplity:

Inspection Date: August 24, 2023

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

HOMES

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

MASTER ENSUITE BATH		
MIRROR	MIRRORS THROUGHOUT NOT INSTALLED	
	SHOWER GLASS NOT INSTALLED	
VANITY CABINETS	CHIPS AT BOTTOM GABLE BELOW LEFT SINK AND RIGHT SINK	
	CHIP ON RIGHT DOOR AND LEFT DOOR BELOW RIGHT SINK AND TOP BANK OF DRAWERS	
	CHIPPED	
COUNTERTOPS	INSPECT SCUFF ON COUNTERTOP LEFT OF SINK	
NOTE:	WINDOW SCREENS AND CRANKS THROUGHOUT NOT INSTALLED	
WALLS	OVER CUT AT CEILING FAN	
MASTER BEDROOM		
WALLS	BLACK MARKS ON STIPPLE CEILING	
BEDROOM #2		
FLOORING	CUT CARPET IN CLOSET	
MAIN BATHROOM		
COUNTERTOPS	COUNTER TOP LEFT OF SINK PEELING AND RIGHT SIDE	
VANITY CABINETS	CHIP AT BOTTOM GABLE BELOW SINK	
UPPER HALL		
WALLS	DENT ON STIPPLE UPPER HALL BY LIGHT FIXTURE	
ELECTRICAL/LIGHTING	LIGHT FIXTURE NOT INSTALLED AT UPPER HALL	
RAILING	SCRATCH AT UPPER RAILING	
BEDROOM #3		
WINDOWS	MISSING WINDOW TRIM ON RIGHT FIXED WINDOW	

Enrollment: Purchaser Name: ????

Sandeep Arora

ZANCOR HOMES PDI Vendor / Builder: 44528

Project: Zancor Homes (Innisfil) Ltd.

Lot / Phase: 354W / 3

Plan: Address:

Municiaplity:
Inspection Date: August 24, 2023

Phone Res:
Phone Bus: (437) 533-2001
Closing Date: September 14, 2023

Inspector: Alexandria Damianidis Page 2 of 3

FOYER/HALL STAIRS VARNISH REQUIRED AT 3,4,5TH TREAD EDGE AT STAIRS FROM 2ND LANDING TO 2ND FLOOR AND NOISING CHIP AT NEWEL POST AT 2ND LANDING AT STAIRS TO 2ND FLOOR AT. TOP CAP LINE AT RISER BELOW NOISING AT 2ND LANDING AT STAIRS TO 2ND FLOOR SECURE TRIM AT 1ST LANDING STAIN REQUIRED AT RAILING TO 2ND FLOOR AND STAIN DRIP ON RAILING BY FRONT DOOR CHIP ON OUTSIDE STRINGER RIGHT OF NOISING AT STAIRS TO 2ND FLOOR CAN SEE FROM FIRST FLOOR HO REQUESTING TO STAIN EDGE OF OF NEWEL POST AT MAIN FLOOR HO REQUESTING TO INSPECT EDGE OF RISER AND STRINGER - ROUGH AND NEWEL. AT 1ST LANDING CHIPPED AT STAIRS TO 2ND FLOOR. HO REQUESTING TO STAIN 2ND TREAD AT STAIRS FROM MAIN FLOOR, AND NOISING 2) STAIN NOISING AT STAIRS TO BSMT 3) REMOVE PAINT FROM PICKET AT STAIRS TO BSMT STAIN REQUIRED AT NOSING AND TREAD EDGES AT STAIRS FROM GARAGE INSPECT RAILING AT STAIRS TO THE BASEMENT VERY ROUGH FRONT DOORS CHIPS ON MIDDLE ASTRICAL AT FRONT DOOR FLOORING CHIP ON 1ST PLANK BY NOSING HARDWOOD MARKED WITH GREEN TAPE AND 4TH FROM BASEMENT STAIRS. BLACK MARK ON STIPPLE CEILING AT ENTRENCE TO KITCHEN WALLS BASEMENT DUCTS NOT CLEANED NOTE: MAIN WATER SHUT OFF VALVLE LEAKING IN BSMT CUT NAILS IN COLD ROOM EXTERIOR NOTE: REMOVE PLASTER ON GARAGE FLOOR SLAB PORCH ADJUST. LEFT COLUMN AT FRONT PORCH GAP AT BOTTOM GAP AT SOFFIT AND STONE AT FRONT PORCH RIGHT SIDE CAN SEE WOOD COLD CELLAR VENT , NOT INSTALLED KITCHEN AS PER LIPGRADES MISSING X2 LIPPER RIGHT AND LEFT CABINET AT WINDOW CARINETS AS PER DRAWINGS CONFIRM IF DESK PANTRY LOWER. RIGHT AND LEFT DOORS SHOULD BE CHIP AT BOTOM GABLE BELOW SINK LEFT SIDE. CHIP BOTTOM RIGHT CABINET BELOW SINK AND RIGHT CABINET AT SINK AT ISLAND CHIP ON BOTTOM RIGHT CABINET RIGHT OF FRIDGE AND INSIDE AT GABLE. CHIP ON PANTRY SHELF INSIDE LEFT OF DESK AND DOOR. CHIP AT KICKPLATE RIGHT OF STOVE. COUNTERTOPS COUNTERTOP AT DESK NOT INSTALLED. DRYWALL REPAIR REQUIRED LEFT OF SLIDING DOOR. WALLS WINDOWS SCREEN DOOR NOT INSTALLED AT KITCHEN LIVING ROOM FLOORING CHIP. 3 AND 21 PLANK FROM ENTRANCE TO LIVING

Enrollment: Purchaser Name: ????

Sandeep Arora

Phone Res:

Date (YYYY/MM/DD)

2023/08/24

Phone Bus: (437) 533-2001 Closing Date: September 14, 2023 Inspector: Alexandria Damianidis



Vendor / Builder: 44528

Project: Zancor Homes (Innisfil) Ltd.

Lot / Phase: 354W / 3

Plan: Address: Municiaplity:

Page 3 of 3 Inspection Date: August 24, 2023

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf. I have inspected my new home and I agree that the description of the items listed on this form are accurate. Sandof of ???? Sandeep Arora Purchaser's Signature Purchaser's Signature Purchaser's Name (print) Purchaser's Name (print) Alexandria Damianidis Designate's Signature Inspector's Name (print) Inspector's Signature Designate's Name (print)

August 24, 2023