



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP
7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W189998
Pack Slip:230738
Service Date: Aug 23, 2023

Priority: Normal

Status:

SCHEDULED

RELEASED

BUILDER

Customer: 611313

City: INNISFIL

Received: Jun 21, 2023

Name: ZANCOR BELLE AIRE SHORES

Service Phone(s):

Time:

Service Fax:

Site Phone:

Order: D389093-1

Site Fax:

Lot#:

326W

Phase:

3

RESIDENT INFORMATION

Home Owner Name: N/A

Address:

N/A

Home Phone(s):

Work Phone(s):

Cell Phone(s):

Email(s):

LINKED ORDER INFORMATION (D389093-1)

Customer: 611313 ZANCOR BELLE AIRE SHORES

Lot #:

326W

Model: 42-05 FISHER/DW

Phase:

3

SERVICE INSTRUCTIONS

BROKEN GLASS PLEASE FIX SEE PICTURES

PARTS REQUIRED

LN	Item Description	Location	PWD	Specification	Size	Options	Qty
181	NEWMAR VINYL CASEMENT			GLASS ONLY - SASH	24.75 X 50.75	AG13 DW/WHLOWE_ARG DW	162.00 1

Problem Description:

Complete

☐ Warranty

Material \$

☐ CHARGEABLES
Material \$ *162.00*

Labour \$

Labour \$ *120.00*

P.O.#:

Cause:

Solution:

Replaced Glass

Date Completed:

Aug 23/23

Approved:

X

Time:

20 mins

Service Signature:

[Signature]
RICHARD



Thank you.
Carm Servello.
Site Supervisor.
Belle Shores Innisfil.



Service Department <servicedept@newmar.com>

326w

1 message

Nathan Simas <nathan@zancorhomes.com> Wed, Jun 21, 2023 at 1:13 PM
To: "servicedept@newmar.com" <servicedept@newmar.com>, "mgreen@newmar.com" <mgreen@newmar.com>

Good afternoon

Broken glass

Thank you,

Nathan Simas
Finishing Supervisor
Belle Aire Shores
Cell # 416-791-9862
nathan@zancorhomes.com

2 attachments



20230621_131050.jpg
3756K



20230621_131041.jpg
3121K