

ANCOR Zancor Homes (Caledon) Ltd.

Warranty Services

Phone: (905) 738-7010 Fax: (905) 738-5948

Work Order

Sept5 12-330 Steve

| 08Jun23 |
|--------------------------------------|
| |
| Caledon Club - Phase: 1B - Lot: 126B |
| 22Aug23 |
| |

Lakshmanaraj Selvarajah - Cell: (416) 527-0363 - (laksh23@hotmail.com) Contact(s):

Ramani Vimaleswaran - Home: (905) 781-4038 - (ramani78@hotmail.com)

Email: laksh23@hotmail.com

| Company: | New Image Kitchens |
|------------|--------------------|
| Attention: | |
| Telephone: | (416) 739-0007 |
| Fax: | (416) 739-7031 |

Please Complete the following items:

| DAI | Туре | Issue | Appt. Date/Time | Notes |
|--------|----------|--|--------------------|-------|
| 160047 | interval | Kitchen- General- Crown molding/ seperating | 03Aug23 /am | |
| 160049 | Interval | Kitchen- General- filler piece not installed below uppercorner | 03Aug23 /am | |


| Date Completed: <u>SED</u> 5 | Homeowner Signature: |
|------------------------------|--|
| | The Homeowner acknowledges and accepts all work has been completed in a workman like manner. |
| Date Completed: | Trade &/or Service Tech. |
| | Signature: |
| | Print Name: |

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Caledon Club - Phase: 1B - Lot: 126B

160047 - 1 - 12 - Crown molding seperating



160049 - 1 - 1233 - filler piece not installed below uppercorner

