Enrollment:

Purchaser Name:

Christine Reta Kahil

Phone Res:

Phone Bus: (416) 200-0442 Closing Date: September 14, 2023 HOMES

Vendor / Builder: 44528

Project: Zancor Homes (Innisfil) Ltd.

Lot / Phase: 326W / 3

Plan: Address: Municiaplity:

Inspection Date: September 08, 2023

Inspector: Gisella Fiore Page 1 of 2 Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be

selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

FOYER/HALL		
STAIRS	SCRATCH ON FIRST SECOND AND THIRD TRIED AT STAIRS FROM SECOND LANDING TO SECOND	
	FLOOR	
	DENT ON STRINGER BELOW NOSING AT SECOND FLOOR	
	CHIP ON RIGHT/LEFT NEWEL POST AT MAIN FLOOR AT TOP CAP AND LEFT NEWELL POST AT MAIN FLOOR CRACKED	
	SCREWPLUG NOT INSTALL THAT RIGHT RAILING AT STAIRS TO SECOND FLOOR	
	SCRATCH ON TRIM ABOVE STRINGER @SMALL FLIGHT OF STAIRS FROM FIRST LANDING TO SECOND LANDING	
	CHIPPER OUTSIDE STRINGER AND NEWEL POST AT SECOND LANDING LEFT SIDE BY PICKET	
WALLS	LINE IN SMOOTH CEILNG IN FRONT OF MUDROOM	 - -
Note		
-	WINDOW SCREENS AND SLIDING DOOR SCREEN THROUGHOUT NOT INSTALLED	
LIVING ROOM		
NOTE:	FIREPLACE GRILL NOT INSTALLED	
KITCHEN		
CABINETS	VALANCE NOT INSTALLED RIGHT OF HOODFAN(IN HOUSE)	
	SCRATCH ON UPPER LEFT CABINET RIGHT OF HOODFAN.	
	BUBBLE AT LOWER RIGHT CABINET RIGHT OF STOVE.	
	CHIP INSIDE 2ND BANK OF DRAWER LEFT OF STOVE.	
	BUBBLE ON BOTTOM RIGHT AND LEFT CABINET BELOW SINK	
	BUBBLE ON LEFT PANEL AT ISLAND FACING FRIDGE BY STOVE / AND RIGHT SIDE FACING D/W/	
	SCRATCH LEFT PANEL	
MASTER ENSUITE BATH		
VANITY CABINETS	SCRATCH ON THE LOWER LEFT CABINET BELOW LEFT SINK	
NOTE:	CLEAN BLACK MARKS FROM COUNTER TOP LEFT OF LEFT SINK	
SHARED ENSUITE		
VANITY CABINETS	SECURE BACK PANEL BELOW LEFT SINK	

Enrollment: Purchaser Name: ?????

EXTERIOR

Purchaser's Name (print)

Designate's Name (print)

Date (YYYY/MM/DD)

Christine Reta Kahil

Purchaser's Signature

Designate's Signature

2023/09/08

Phone Res: Phone Bus: (416) 200-0442 Closing Date: September 14, 2023

Inspector: Gisella Fiore

ZANCOR

Page 2 of 2

Vendor / Builder: 44528

Project: Zancor Homes (Innisfil) Ltd.

Purchaser's Signature

Inspector's Signature

Lot / Phase: 326W / 3

Plan: Address: Municiaplity:

Inspection Date: September 08, 2023

NOTE:	DOWNSPOUT NOT INSTALLED FRONT PORCH CAP AT RAILING MISSING, RIGHT SIDE					
	,					
THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.						
* Purchasers or owners who inte designate to sign this form on th	nd to designate someone to conduct the PDI in their place should ensure they provide eir behalf.	written authority to the vendor/builder aut	thorizing the			
I have inspected my new home and I agree that the description of the items listed on this form are accurate.						
?????	Christine Reta Kahil					

Purchaser's Name (print)

Inspector's Name (print)

September 08, 2023

Gisella Fiore