Enrollment:

Purchaser Name: ??????

Amrinder Singh

Phone Res:

Phone Bus: (365) 773-4000 Closing Date: September 28, 2023 HOMES

selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: Block 151 Unit 3 / 1

Plan: Address: Municiaplity:

Inspection Date: September 27, 2023

Inspector: Alexandria Damianidis

Page 1 of 2 Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

KITCHEN		
CABINETS	CHIP AT BOTTOM KICKPLATE BELOW SINK AT ISLAND RIGHT SIDE	
	CHIP AT BOTTOM GABLE BELOW SINK AND EDGE PEELING AT ISLAND	
	CHIP AT UPPER LEFT CABINET ABOVE HOOD FAN	
	CHIP AT UPPER CABINET LEFT OF HOOD FAN	
	CHIP AT ISLAND FACING FAMILY AREA	
FAMILY ROOM		
WINDOWS	SCREEN DOOR NOT INSTALLED	
FOYER/HALL		
STAIRS	CHIP AT FIRST HARD WOOD PLANK BY NOISING AT LANDING TO 3RD FLOOR	
	CHIP AT INSIDE STRINGER AT 3RD FLOOR BEST SIDE NOISING RIGHT SIDE	
	CHIP AT 10TH TREAD AND WOOD PIECE BELOW STRINGER AT STAIRS FROM 2ND FLOOR TO	
	LANDING TO 3RD FLOOR	
	SAW CUT ON POST PILLOW NOSING AND CHIP ON STRINGER LEFT OF NOSING AT LANDING TO SECOND FLOOR FROM MAIN FLOOR	
	WATER STAINS ON TREAD BELOW NOSING AT LANDING TO SECOND-FLOOR BLACK MARKS	
	CHIP ON NOSING AT SECOND FLOOR RIGHT SIDE BELOW NEWEL POST.	
	CALL KING REQUIRED AT STAIRS TO BASEMAN ON THE RIGHT AND LEFT SIDE OF STAIRS	
	STRINGER BELOW NOSING AT STAIRS TO BASEMENT LARGE BLACK STAIN	
CLOSET	LARGE GAP IN BETWEEN CLOSET DOORS IN FRONT OF FRONT DOOR AT MAIN FLOOR	
MASTER ENSUITE BATH		
NOTE:	DAMAGED ASTRICAL AT BALCONY DOOR	
SHOWER ENCLOSURE	SHOWER GLASS NOT INSTALLED	
MASTER BEDROOM		
WINDOWS	DAMAGED ASTRICAL AT BALCONY DOOR 2) SCREW PLUGS NOT INSTALLED	

Enrollment: Purchaser Name: ??????

Amrinder Singh

Phone Res:

Phone Bus: (365) 773-4000 **Closing Date:** September 28, 2023

Inspector: Alexandria Damianidis

ZANCOR HOMES PDI Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: Block 151 Unit 3 / 1

Plan: Address: Municiaplity:

Page 2 of 2 Inspection Date: September 27, 2023

EXTERIOR		
NOTE:	CHIPS AT EXTERIOR DOOR TRIM AT PATIO DOOR AT BALCONY IN MASTER BED	
	POWER WASH REQUIRED ON BRICKS THROUGHOUT	
BRICKS	DAMAGED SILL RIGHT OF LIGHT FIXTURE AT REAR PATIO AT 3RD FLOOR	
GENERAL COMMENTS		
NOTE:	HOMEOWNER UNHAPPY, NAIL POPS ON TRIM AROUND ALL DOORS THROUGHOUT HOME	
	AC NOT INSTALLED	
BEDROOM #2		
WALK IN CLOSET	YELLOW STAINS IN CLOSET - PAINT	
POWDER ROOM		
NOTE:	FIRST FLOOR POWEDER ROOM - CHIP AT RIGHT GABLE AT FLOOR LINE	

A REFERENCE FOR FUTURE WAR	RANTY REQUESTS. to designate someone to conduct the PDI in the	E HOME'S CONDITION BEFORE THE PURCHASI	
I have inspected my new home and	I agree that the description of the items listed	on this form are accurate.	
??????	45	Amrinder Singh	
Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature
		Alexandria Damianidis	AD
Designate's Name (print)	Designate's Signature	Inspector's Name (print)	Inspector's Signature
Date (YYYY/MM/DD)	2023/09/27	September 27, 2023	