Enrollment:

Purchaser Name: Lucas SIGNORILE

Isabella Esilda LAMANTIA

Phone Res: (416) 420-1784 Phone Bus: (647) 980-7682 Closing Date: October 30, 2023 HOMES

Vendor / Builder:

Project: Zancor Oakville Ltd.

Lot / Phase: 424 / 1

Plan:

Address: 2450 Old Bronte Road, Suite 424

Municiaplity:

Inspection Date: September 28, 2023

Inspector: Alexandria Damianidis Page 1 of 2 Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be

selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

## DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

## **OPERATING CONDITION**

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

KITCHEN		
KITCHEN		
CABINETS	CHIPS AT BOTTOM GABLE BELOW SINK AND AT KICKPLATE BELOW AND ON DOOR AND ON	 ·
	RIGHT CABINET DOOR	
	CHIPS ON DW PANEL	 
	CHIP AT UPPER CABINET ABOVE MICROWAVE	 
	CHIP AT BOTTOM BANK OF DRAWER	 
	CHIPS AT FILLER PIECE LEFT OF FRIDGE AND SCUFF MARKS ON FREEZER PANNEL	 
	CHIP ON KICKPLATE BELOW BANK OF DRAWERS	 
	REMOVE SCUFF MARKS ON UPPER CABINET RIGHT OF MICROWAVE	 
	ADJUST UPPER CABINET SHELF LEFT OF MICROWAVE ON ANGLE	 
NOTE:	INSPECT FREEZER - LOTS OF ICE INSIDE AND ADJUST WEATHER STRIP	 
	BOTTOM DRAWER OF STOVE NOT CLOSING PROPERLY	 
FOYER/HALL		
CLOSET	ROGERS PANEL NOT FLUSH WITH THE WALL	 
MASTER BEDROOM		
TRIM	SCREW MISSING AT LATCH AT BEDROOM DOOR	 
WINDOWS	WINDOW SCREEN MISSING	 

Enrollment:

Purchaser Name: Lucas SIGNORILE

Isabella Esilda LAMANTIA

Phone Res: (416) 420-1784 Phone Bus: (647) 980-7682 Closing Date: October 30, 2023 Inspector: Alexandria Damianidis



Vendor / Builder:

Project: Zancor Oakville Ltd.

Lot / Phase: 424 / 1 Plan:

Address: 2450 Old Bronte Road, Suite 424

Municiaplity:

Inspection Date: September 28, 2023

Page 2 of 2

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.  * Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.					
I have inspected my new home and I agree that the description of the items listed on this form are accurate.					
Lucas SIGNORILE	\$.	Isabella Esilda LAMANTIA			
Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature		
		Alexandria Damianidis	AD		
Designate's Name (print)	Designate's Signature	Inspector's Name (print)	Inspector's Signature		
Date (YYYY/MM/DD)	2023/09/28	September 28, 2023			