



**Zancor Homes (Wasaga River) Ltd.**  
**Warranty Services**  
**Phone: (905) 738-7010**  
**Fax: (905) 738-5948**

**Work Order**

Mo  
Sep 27  
12-4

**Closing Date:** 22Sep23

**Address:**

**Location:** Rivers Edge - Phase: 1 - Lot: 118

**Today's Date:** 15Sep23

**Contact(s):** Paul, W Haffenden - Home: (647) 298-4991 - (p.haffenden@rogers.com)  
Jane, E Haffenden - Home: (416) 903-5715 - (janehaffenden@rogers.com)

**Email:** p.haffenden@rogers.com

**Company:** New Image Kitchens

**Attention:**

**Telephone:** (416) 739-0007

**Fax:** (416) 739-7031

✓ 3 Sets of  
Soft close  
TRACKS

**Please Complete the following items:**

DAI	Type	Issue		Appt. Date/Time	Notes
162826	PDI	Main Bathroom- General- vanity drawers, not self closing properly			D

**Date Completed:** 9/27/23

**Homeowner Signature:** [Signature]

The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

**Date Completed:** \_\_\_\_\_

**Trade &/or Service Tech.**

**Signature:** [Signature]

**Print Name:** [Signature]

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

**Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.**

  
**Robert Cioffi**

**From:** Austin Kelly <Austin@zancorhomes.com>  
**Sent:** Thursday, September 7, 2023 12:05 PM  
**To:** Robert Cioffi  
**Cc:** Mary Ielpo  
**Subject:** Rivers Edge 118/331

Mo  
Sept 14  
Key

Hey Rob,

Please schedule the below as soon as you can.

118:

- loft bath, chips on gable
- Master ensuite, chip on floor under right sink
- Main bath Drawers get stuck, adjust
- Kitchen
  - o Chip inside right door lower cabinet left of stove
  - o Left of drawers, floor chipped
  - o Upper far left of stove, chip @ handle
  - o 2 cabinets right of fridge, floor chipped
  - o Chip @ lower cabinet right of fridge
  - o Adjust cabinets
  - o Island, gable @ top left chipped

D

331:

- Master ensuite
  - o Chip @ upper gable middle cabinet
- Main bath
  - o Red stain @ counter by left cabinet
  - o Chip upper + lower gable below sink
- 2<sup>nd</sup> ensuite
  - o Chip @ upper gable
- Kitchen
  - o Couple cabinet doors not installed
  - o Adjust 2<sup>nd</sup>/3<sup>rd</sup> drawers
  - o Chip @ lower gable cabinet left of sink
  - o Chips @ upper gable right of stove
  - o Chipped shelf lower gable cabinet far left from fridge
  - o Handle loose lower left of fridge
  - o Chip upper gable right of fridge
- Laundry
  - o Chip left cabinet
  - o Stain on countertop

Thank you,