Enrollment:

Purchaser Name:

Chun, C Chang

Phone Res:

Phone Bus: (647) 390-8890

HOMES

Lot / Phase: 359W / 3

Plan:

Vendor / Builder: 44528

Address: Municiaplity:

Inspection Date: September 29, 2023

Project: Zancor Homes (Innisfil) Ltd.

Closing Date: October 05, 2023 Inspector: Alexandria Damianidis

Page 1 of 3 Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

UPPER HALL		
FLOORING	REMOVE STAINS ON CARPET AT UPPER HAL BELOW SMOKE DETECTOR	
LAUNDRY ROOM		
FLOORING	TILE BASEBOARD NOT INSATALLED/CUT SHORT	
FOYER/HALL		
STAIRS	CHIPS ON FIRST HARDWOOD PLANK AT FIRST LANDING AT STAIRS TO 2ND FLOOR	
	CHIP AT NOSING AT FIRST LANDING AT STAIRS TO 2ND FLOOR	
	BIG GAP BETWEEN NEWEL POST AND TREAD AT STAIRS AT 2ND FLOOR	
	VARNISH REQUIRED ON THIRD TREAD AT FIRST LANDING AT STAIRS TO SECOND FLOOR AND	
	VARNISH REQUIRED ON OUTSIDE STRINGER AT FIRST LANDING AT STAIRS TO SECOND FLOOR	
	VARNISH REQUIRED ON NOSING AT STAIRS TO BASEMENT	
	AS P[ER HO, FIRST HARDWOOD P[LANK RAISED AT STAIRS TO BASEMENT - NOT FLUSH	
FLOORING	CHIP ON EIGHTH HARDWOOD PLANK IN FRONT OF POWDER	
FRONT DOORS	CHIPS I ASTRICAL AT FRONT DOOR	
KITCHEN		
CABINETS	REMOVE PAPER BELOW CABINETS THROUGHOUT KITCHEN	
	CHIPS AT UPPER GABLE LEFT OF STOVE CUT OUT	
	CHIPS AT FILLER PIECE AT LOWER CABINETS LEFT OF SINK AND SCUFF MARK ON CABINET BESIDE	
	CHIP AT LOWER CABINET BELOW SINK, AND SCUFF MARKS/GLUE	
	CHIPS ON KICKPLATE AT ISLAND FACING LIVING AREA AND BESIDE DESK AT KICKPLATE AND RIGHT AND LEFT GABLE BESIDE	
	REMOVE/REPLACE HANDLES AT DESK AREA - PAINT ON BOTH AND ON CABINETS ABOVE FRIDGE 2) CHIP ON DESK CABINET RIGHT SIDE AND AT GABLE ABOVE	
	CHIPS AT FRIDGE GABLE RIGHT SIDE	
	CHIPS AT UPPER CABINET AT SERVERS AREA LEFT SIDE, AND AT LEFT CABINET BELOW BOTTOM GABLE. REMOVE GLUE/SCUFF MARKS ON BOTTOM RIGHT CABINET	
	AS PER HO ISLAND INSTALLED INCORRECT, OVERHANG SHOULD BE 30 CM AND IS ONLY 15	

Enrollment: Purchaser Name: ?????

Chun, C Chang

ZANCOR

Vendor / Builder: 44528

Project: Zancor Homes (Innisfil) Ltd.

Lot / Phase: 359W / 3

Inspection Date: September 29, 2023

Plan: Address:

Municiaplity:

Phone Res:

LIVING ROOM

Phone Bus: (647) 390-8890

Closing Date: October 05, 2023

Inspector: Alexandria Damianidis

Page 2 of 3

KITCHEN **FLOORING** CHIP ON HARDWOOD PLANK INFRONT OF SINK, 3RD HARDWOOD PLANK FROM ISLAND NAIL AT FIFTH HARDWOOD PLAYING IN FRONT OF SINK INSPECT SQUEAK AT ISLAND INFRNT OF FRIDGE EXTERIOR REMOVE PLASTER FROM GARAGE FLOOR SLAB NOTE: CLIP MISSING ON METRE BASE SERVICE SIDE AND BESIDE AC FLAT MISSING AT EXHAUST FAN AT LEFT SIDE OF HOME DECK MOTOR MISSING AT LEFT PORCH COLUMN AS PER HO LARGE GAP IN BETWEEN BRICKS RIGHT SIDE OF DOOR 2)MORTAR REQUIRED IN **BRICKS** BETWEEN GARAGE POWER WASH REQUIRED AT HOME AND AT BALCONY ABOVE FRONT PORCH PORCH NAILS AT PORCH AND BIG GAPS GUTTERS DAMAGED ABOVE FRONT PORCH MOTOR MISSING AT FRONT WINDOW LEFT SIDE OF HOME MASTER ENSUITE BATH

SHOWER ENCLOSURE CHIP AT WALL TILE ACROSS FROM PLUMBING SECOND TITLE FROM CEILING RIGHT SIDE AND 5TH TILE BELOW AND AT 1ST TILE RIGHT OF PLUMBING MASTER BEDROOM WALLS PAINT ATTIC HATCH FLOORING INSPECT CREAK/NOISE INFRONT OF ENSUITE WASHROOM AS PER HO SHARED ENSUITE FLOORING TUCK CARPET AT ENTRANCE TO SHARED BATH ON BOTH SIDES

ELECTRICAL/LIGHTING REPLACE FIREPLACE LIGHT SWITCH HAS BLUE PEN MARK ON IT

Enrollment: Purchaser Name: ?????

Chun, C Chang

Phone Res:

Date (YYYY/MM/DD)

2023/09/29

Phone Bus: (647) 390-8890 Closing Date: October 05, 2023 Inspector: Alexandria Damianidis



Vendor / Builder: 44528

Project: Zancor Homes (Innisfil) Ltd.

Lot / Phase: 359W / 3

Plan: Address: Municiaplity:

Inspection Date: September 29, 2023

Page 3 of 3

A REFERENCE FOR FUTURE WAR	RANTY REQUESTS. to designate someone to conduct the PDI in th	E HOME'S CONDITION BEFORE THE PURCHASI neir place should ensure they provide written auth	
I have inspected my new home and	I agree that the description of the items listed	on this form are accurate.	
?????	N	Chun, C Chang	
Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature
		Alexandria Damianidis	AD
Designate's Name (print)	Designate's Signature	Inspector's Name (print)	Inspector's Signature

September 29, 2023