


<b>Enrollment:</b> <b>Purchaser Name:</b> Melissa HUDAYIOGLU  <b>Phone Res:</b> (647) 695-5500 <b>Phone Bus:</b> <b>Closing Date:</b> November 06, 2023 <b>Inspector:</b> Gisella Fiore		<b>Vendor / Builder:</b> <b>Project:</b> Zancor Oakville Ltd. <b>Lot / Phase:</b> 616 / 1 <b>Plan:</b> <b>Address:</b> 2450 Old Bronte Road, Suite 616 <b>Municipality:</b> <b>Inspection Date:</b> October 13, 2023
<b>Page 1 of 2</b>		

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

- |   |   |
|---|---|
| <b>DAMAGED, INCOMPLETE OR MISSING</b> <ul style="list-style-type: none"><li>• Windows, side lights and other glazing. Window and door screens</li><li>• Bathtub sinks and toilets</li><li>• Bathroom accessories if provided</li><li>• Mirrors, counter tops and cabinetry</li><li>• Flooring (hardwood, vinyl, ceramic tiles, carpeting)</li><li>• Interior finished and trim carpentry</li><li>• Furnace</li><li>• Hot water heater, if provided (not rental)</li><li>• Exterior finished, driveways, walkways, decks and landscaping</li></ul> | <b>OPERATING CONDITION</b> <ul style="list-style-type: none"><li>• Windows, interior and exterior doors. Door locks</li><li>• Faucets: Kitchen, bathroom, laundry room</li><li>• Exhaust fans (kitchen, bathrooms) if provided</li><li>• Electrical outlets and fixtures</li><li>• Gas fireplaces, incl.circulation fans, if provided</li><li>• Heat Recovery Ventilation system, if provided</li><li>• Heating system</li><li>• Hot water heater, if provided (not rental)</li><li>• Air conditioning system, if provided and if conditions permit</li></ul> |
|---|---|

<b>KITCHEN</b>	
CABINETS	DAMAGED BOTTOM PANEL BELOW SINK AT LEFT CABINET INSIDE. DENT ON UPPER LEFT CABINET LEFT OF MICROWAVE.
NOTE:	DENT ON MICROWAVE ABOVE HANDLE.
<b>MASTER BEDROOM</b>	
NOTE:	SCREW NOT INSTALLED AT BREAKER PANEL

**Enrollment:**  
**Purchaser Name:** Melissa HUDAYIOGLU  
  
**Phone Res:** (647) 695-5500  
**Phone Bus:**  
**Closing Date:** November 06, 2023  
**Inspector:** Gisella Fiore



Page 2 of 2

**Vendor / Builder:**  
**Project:** Zancor Oakville Ltd.  
**Lot / Phase:** 616 / 1  
**Plan:**  
**Address:** 2450 Old Bronte Road, Suite 616  
**Municipality:**  
**Inspection Date:** October 13, 2023

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

*\* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.*

I have inspected my new home and I agree that the description of the items listed on this form are accurate.

Melissa HUDAYIOGLU

A handwritten signature in blue ink, appearing to read "Melissa Hudayioğlu".

Purchaser's Name (print)

Purchaser's Signature

Purchaser's Name (print)

Purchaser's Signature

Gisella Fiore

A handwritten signature in blue ink, appearing to read "Gisella Fiore".

Designate's Name (print)

Designate's Signature

Inspector's Name (print)

Inspector's Signature

Date (YYYY/MM/DD)

2023/10/13

October 13, 2023