Enrollment:

Purchaser Name: ?????

Sonia Aggarwal

- Sulla Ayyan

Phone Res:

Phone Bus: (647) 963-9966 **Closing Date:** September 22, 2022

ANCOR HOMES Vendor / Builder: 44528

Project: Zancor Homes (Innisfil) Ltd.

Lot / Phase: 350W / 3

Plan: Address: Municiaplity:

Inspection Date: October 16, 2023

Inspector: Alexandria Damianidis Page 1 of 2

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

KITCHEN			
CABINETS	CHIPS AT RIGHT GABLE BESIDE HOOD FAN AND ON CABINET BESIDE BOTH CORNERS	 _	
	CHIPS ON SHELF AT BOTTOM CABINET LEFT OF HOOD FAN	 _	
	CHIP ON CABINET AT ISLAND FACING LIVING AREA	 	
COUNTERTOPS	REMOVE PAINT FROM COUNTER TOP THROUGHOUT -MULTIPLE AREAS	 	
FOYER/HALL			
STAIRS	HOLE/GAP AT FIRST TREAD, BESIDE LEFT NEWEL POST AT MAIL FLOOR		
	VARNISH DRIP ON NOISING AND WHITE PAINT AT 2ND FLOOR - ALSO REMOVE PAINT FROM	_	
	PICKETS		
WALLS	TOUCH UP, STIPPLE BY SMOKE DETECTOR IN FRONT OF GARAGE DOOR ENTRANCE	 -	
EXTERIOR			
NOTE:	REMOVE PLASTER FROM GARAGE FLOOR SLAB		
	GARAGE CEILING AND WALLS NOT PAINTED -PREPPED ONLY	 _	
MASTER ENSUITE BATH			
FAUCETS/PLUMBING	UPGRADED BATH ACCESSORIES NOT SUPPLIED THROUGHOUT - LEAVE IN HOME DO NOT		
	INSTAL AS PER EXTRAS		
VANITY CABINETS	REMOVE PAINT FROM CABINETS RIGHT OF SINK	 _	
NOTE:	OVER CUT AT POT LIGHT TILE	 	
BEDROOM #3			
WALLS	TOUCH UP, STIPPLE AT ENTRANCE TO BED	-	
MAIN BATHROOM			
TUB	SCRATCHES AND PAINT ON TUB IN MULTIPLE AREAS	_	
LIVING ROOM			
ELECTRICAL/LIGHTING	FIREPLACE NOT TURNING ON AND SCREEN BENT AND TRIM AT BOTTOM CUT NOT STARIGHT	 	
POWDER ROOM			
ELECTRICAL/LIGHTIN	LIGHTBULB MISSING		

Enrollment: Purchaser Name: ?????

Sonia Aggarwal

Phone Res:

Phone Bus: (647) 963-9966

Closing Date: September 22, 2022

Inspector: Alexandria Damianidis

ZANCOR HOMES Vendor / Builder: 44528

Project: Zancor Homes (Innisfil) Ltd.

Lot / Phase: 350W / 3

Plan: Address: Municiaplity:

Inspection Date: October 16, 2023

POWDER ROOM		
SINK/FAUCET/PLUMBING	REMOVE PAINT ON SINK BELOW PLUMBING	

Page 2 of 2

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf. I have inspected my new home and I agree that the description of the items listed on this form are accurate. ????? Sonia Aggarwal Purchaser's Signature Purchaser's Name (print) Purchaser's Signature Purchaser's Name (print) Alexandria Damianidis Designate's Name (print) Designate's Signature Inspector's Name (print) Inspector's Signature 2023/10/16 Date (YYYY/MM/DD) October 16, 2023