Enrollment:

Purchaser Name: Junifen Villalba

Perlita Vizcarra Villalba

Phone Res: (905) 738-0326 Phone Bus: (647) 992-8591 Closing Date: October 12, 2023 Inspector: Alexandria Damianidis HOMES

selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

Vendor / Builder: 44528

Project: Zancor Homes (Innisfil) Ltd.

Lot / Phase: 77W / 3 Plan:

Address: Municiaplity:

Inspection Date: October 16, 2023

Page 1 of 2 Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

EXTERIOR		
NOTE:	BASEMENT WINDOW CRACKED BESIDE DECK	
GARAGE DOORS	SECURE WEATHER STRIP RIGHT AND LEFT SIDE	
PAINT	EXTERIOR PAINT NOT COMPLETE	
BASEMENT		
COLD ROOM	CUT NAILS IN COLD ROOM CEILING	
FURNACE	INSPECT WATER BY FURNACE AS PER HO - VALVE AT LEFT SIDE OF FURNACE MISSING PIPE	
POWDER ROOM		
NOTE:	SECURE CEILING FAN	
	ROUGH DRYWALL AT CORNERS ABOVE DOOR	
MIRROR	MIRROR NOT INSTALLED	
LIVING ROOM		
TRIM	HOMEOWNER UNHAPPY WITH WAY TRIM PIECE IS CUT	
ELECTRICAL/LIGHTING	INSPECT WALL LIGHT FLICKERING	
NOTE		
*	CAULK WINDOWS THROUGHOUT HOME AS PER HOMEOWNER	 <u> </u>
FOYER/HALL		
FRONT DOORS	CHIPS AT ASTRICAL AT FRONT DOOR	
STAIRS	FILL GAP AT TILE AND NOISING AT STAIRS TO BSMT	
	STAIN TOUCH UP REQUIRED AT NEWEL POST AT 1ST LANDING	
	SCRATCH AT 1ST NOISING AT 2ND FLOOR	
BEDROOM 3 ENSUITE		
TRIM	TRIM CUT SHORT BELOW WINDOW	
VANITY CABINETS	WATER DAMAGE AT BOTTOM GABLES	

Enrollment:

Date (YYYY/MM/DD)

Purchaser Name: Junifen Villalba

Perlita Vizcarra Villalba

2023/10/16

Phone Res: (905) 738-0326
Phone Bus: (647) 992-8591
Closing Date: October 12, 2023
Inspector: Alexandria Damianidis

ZANCOR HOMES PDI Vendor / Builder: 44528

Project: Zancor Homes (Innisfil) Ltd.

Lot / Phase: 77W / 3 Plan:

Address: Municiaplity:

Page 2 of 2 Inspection Date: October 16, 2023

LAUNDRY ROOM			
FLOORING	TILE BASEBOARD RIGHT OF WINDOW WAVY		
UPPER HALL			
WALLS	BUDGE IN DRYWALL AT ENTRANCE TO MAST	ER	
SHARED ENSUITE			
TUB	CAULK BASE OF TUB		
MASTER ENSUITE BATH			
SHOWER ENCLOSURE	MIRRORS AND SHOWER GLASS NOT COMPLE	ETE	
KITCHEN			
ELECTRICAL/LIGHTING	AS PER HO ELECTRICAL ROUGH IN FOR LIG DRAWINGS	HTS ABOVE ISLAND NOT ENTERED AS PER	
CABINETS	CHIPS AT BOTTOM GABLE AT BOTTOM CABIN	NET RIGHTY OF FRIDGE	
	CHIPS AT FILLER PIECE AT BOTTOM CABINE	TS LEFT OF STOVE	
	CHIPS AT PIE CABINET		
	CHIPS AT FILLER PIECE AT UPPER CABINET	CORNER LEFT OF STOVE CORNER	
NOTE:	CHIPS AT LOCK AT SLIDING DOOR		
TRIM	HOMEOWNER UNHAPPY WITH TRIM		
A REFERENCE FOR FUTURI * Purchasers or owners who i designate to sign this form or	intend to designate someone to conduct the PDI in th	neir place should ensure they provide written auth	
		Perilla Vizcaria Villalba	
Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature
		Alexandria Damianidis	
Designate's Name (print)	Designate's Signature	Inspector's Name (print)	Inspector's Signature

October 16, 2023