



NEWMAR WINDOW MFG. INC.  
ALPA LUMBER GROUP

8 EDVAC DRIVE, BRAMPTON ON L6S 5P2  
TEL (905) 672-1233 FAX (905) 672-1076

WO # W19982

Pack Slip:5968

Service Date: Oct 20, 2023

Priority: Normal

Status: SCHEDULED

**BUILDER**

Customer: 8030030

Name: ZANCOR THE BRANCH CONDOS

Service Fax:

Site Fax:

City: OAKVILLE

Service Phone(s):

Site Phone: (416) 566-2066

Lot#: 7TH FLOOR

Received: Oct 19, 2023

Time:

Order: H801168-1

Phase: 701

**RESIDENT INFORMATION**

Home Owner Name:

Home Phone(s):

Cell Phone(s):

Address:

Work Phone(s):

Email(s):

**LINKED ORDER INFORMATION (H801168-1)**

Customer: 8030030 ZANCOR THE BRANCH CONDOS

Lot #: 7TH FLOOR

Phase:

House Model: 7TH FLOOR

Elevation:

**SERVICE INSTRUCTIONS**

\*\*\*CLOSING ON NOVEMBER 7TH 2023\*\*\*

INVESTIGATE AND CORRECT

DAI #165088 - PDI - MASTER BEDROOM - WINDOWS - CHIPS ON WINDOW CRANK RIGHT SIDE AND MULIN RIGHT SIDE DENTED

DAI #165089 - PDI - LIVING ROOM - WINDOWS - ADJUST SLIDING DOOR NOT LOCKING

DAI #165091 - PDI - KITCHEN - WINDOWS - DAMAGE MULLIN AT WINDOW RIGHT OF STOVE AND SCREEN NOT INSTALLED

Problem Description:

☐ Warranty

Material \$

Labour \$

☐ CHARGEABLES

Material \$

Labour \$

P.O.#:


Cause:

Solution:

Date Completed:

Approved:

Time:

Service Signature: 

STEEVEN