Enrollment:

Purchaser Name: Phone Res:

Rishi Sharma

HOMES

Vendor / Builder: 44528

Project: Zancor Homes (Innisfil) Ltd.

Lot / Phase: 330W / 3

Plan: Address:

Municiaplity:

Inspection Date: October 23, 2023

Phone Bus: (647) 985-9101 Closing Date: September 28, 2023

Inspector: Alexandria Damianidis

Page 1 of 2 Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

FOYER/HALL		
	OTAIN DECUMED AT FIRST TREAD ONLIFET ONE NEWEL DOOT AT MAIN FLOOR ARD TREAD	
STAIRS	STAIN REQUIRED AT FIRST TREAD ON LEFT SIDE, NEWEL POST AT MAIN FLOOR, 3RD TREAD,	
	5TH TREAD, 6TH TREAD, 7TH TREAD, 8TH TREAD, 10TH TREAD, NOISING AT FIRST LANDING,	
	1ST TREAD AFTER 1ST LANDING, AND NEWEL POST AT 2ND FLOOR LEFT SIDE	
	CHIPS AT NEWEL POST AT MAIN FLOOR	
	STAIN REQUIRED AT 1ST AND 2ND TREAD AT STAIRS TO BSMT AND ON NOSING AT STAIRS TO BSMT	
	CHIP ON 4TH TREAD AT STAIRS TO 2ND FLOOR	
	BIG GAP BETWEEN NOSING AT NEWEL POST AT 2ND FLOOR	
	CHIP AT NEWEL POST AT 2ND FLOOR LEFT SIDE AT FLOOR LINE	
LAUNDRY ROOM		
FLOORING	SHOE MOLE NOT INSTALLED	
MASTER ENSUITE BATH		
VANITY CABINETS	CHIPS AT BOTTOM GABLE BELOW LEFT SINK	
	CHIPS AT BOTTOM GABLE BELOW RIGHT SINK	
MAIN BATHROOM		
COUNTERTOPS	REMOVE STAINS/GLUE ON COUNTER TOP AT BEDROOM 3 AND 4 ENSUITE SHARED	
	CHIPS ON SIDE SPLASH RIGHT SIDE	
	CHIPS AT SIDE SPLASH LEFT AND RIGHT SIDE	
MASTER BEDROOM		
WALLS	STIPPLE REPAIR REQUIRED	
WALK IN CLOSET	ATTACH HATCH NOT INSTALLED	

Enrollment: Purchaser Name: ????

Phone Res:

Rishi Sharma

Phone Bus: (647) 985-9101

Closing Date: September 28, 2023



Vendor / Builder: 44528

Project: Zancor Homes (Innisfil) Ltd.

Lot / Phase: 330W / 3

Plan: Address: Municiaplity:

Inspector: Alexandria Damianidis Page 2 of 2 Inspection Date: October 23, 2023

KITCHEN		
CABINETS	CHIPS AT BOTTOM GABLE LEFT OF FRIDGE	
	CHIPS AT FRIDGE GABLES LEFT AND RIGHT SIDE	
	CHIP AT UPPER CABINET FACE RIGHT CORNER LEFT OF STOVE	
	CHIP AT UPPER CABINET RIGHT OF STOVE AND ON FACE OF CABINET RIGHT SIDE CORNER	
	CHIP AT BOTTOM GABLE BELOW SINK LEFT CABINET	
	CHIP AT LOWER CABINET BOTTOM GABLE AND ON SHELF RIGHT OF STOVE AND CORNER CABINET	
	CHIPS AT ISLAND GABLES AT FLOOR LINE, INFRONT OF SINK AND INFRONT OF FRIDGE CUT OUT	
	DAMAGED LOWER CABINET AT SEVERY	
SHARED ENSUITE		
TUB	REMOVE PAINT FROM TUB IN BOTH BATHS	
FAMILY ROOM		
FLOORING	CHIP AT HARDWOOD PLANK BY TILE IN KITCHEN	
EXTERIOR		
NOTE:	REMOVE PLASTER FROM GARAGE FLOOR	

A REFERENCE FOR FUTURE WARF	NANTY REQUESTS. In designate someone to conduct the PDI in the	E HOME'S CONDITION BEFORE THE PURCHASS veir place should ensure they provide written auth	
I have inspected my new home and I	agree that the description of the items listed	on this form are accurate.	
	7		
????	4	Rishi Sharma	
Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature
			AD
		Alexandria Damianidis	
Designate's Name (print)	Designate's Signature	Inspector's Name (print)	Inspector's Signature
Date (YYYY/MM/DD)	2023/10/23	October 23, 2023	