Enrollment:

Purchaser Name: ??????

Sumit Chauhan

Phone Res:

none nes.

Phone Bus: (416) 897-3776 **Closing Date:** November 09, 2023

Inspector: Gisella Fiore Page 1 of 2

ZANCOR

HOMES

Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: Block 151 Unit 2 / 1

Plan: Address: Municiaplity:

Inspection Date: October 27, 2023

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

MASTER ENSUITE BATH			
FLOORING	ADJUST SHIM AT ENTRANCE TO BATHROOM.		
VANITY CABINETS	SMALL CHIP CABINET LEFT AND RIGHT SIDE BELOW SINK.		
MASTER BEDROOM			
WINDOWS	ADJUST DOOR NOT CLOSING AND MISSING SCREW COVER HOLES		
NOTE:	MISSING DOOR STOP INSIDE CLOSET.		
MAIN BATHROOM		,	
COUNTERTOPS	CHIP AT LEFT COUNTERTOP EDGE.		
	REMOVE EXCESS GROUPS FROM FLOOR AND WALL TILES		
BEDROOM #2			
WINDOWS	ADJUST WINDOW VERY HARD TO CLOSE.		
FOYER/HALL			
STAIRS	VARNISH REQUIRED AT UPPER 3RD FLOOR RAILING BY POST.		
	REMOVE PAINT OFF PICKETS THROUGHOUT.		
	REPLACE INSIDE STRINGER BY NOSING AT 3RD FLOOR		
	DAMAGED OUTSIDE STRINGER BY POST RIGHT OF NOSING AT LANDING TOO 3RD FLOOR AND BY 4TH TREAD		
	CHIP ON RIGHT NEWEL AT STAIRS TOO 3RD FLOOR FROM MAIN		
	CRACK TRIMMED BELOW RISER AT MAIN FLOOR TO 2ND FLOR NEXT TO BASEMENT DOOR		
NOTE:	REMOVE PAINT FROM RIGHT CABINETRY.		
	SECURE FAN AT CEILING.		
	ADJUST LOOK AT FIX DOOR TOP CANNOT OPEN		
LIVING ROOM			
NOTE:	REMOVE SPECKLE INSIDE FIREPLACE LEFT SIDE.		

Enrollment:

Purchaser Name: ??????

Sumit Chauhan

Phone Res:

Phone Bus: (416) 897-3776
Closing Date: November 09, 2023
Inspector: Gisella Fiore



Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: Block 151 Unit 2 / 1

Plan: Address: Municiaplity:

Page 2 of 2 Inspection Date: October 27, 2023

POWDER ROOM		
NOTE:	CHIP ON BOTTOM RIGHT AND LEFT CABINET BELOW SINK. AND FILL NAIL HOLES KICKPLATE	
	BELOW.	
	SCRATCH ON LEFT SIDE OF COUNTERTOP	
KITCHEN		
CABINETS	CHIP INSIDE 1 AND 2 POT DRAWER RIGHT OF FRIDGE.	
	SMALL CHIP INSIDE SHELF RIGHT OF GARBAGE DRAWERS	
	DAMAGED ISLAND GABLE FACING BREAKFAST AREA BY FEW.	
EXTERIOR		
NOTE:	INSPECT ALMUINUM DENTED FOR LOW RAILING AT UPPER RAILING NEXT TO WOODEN FLOOR	
	LEFT AND RIGHT SIDE	
	REMOVE MEDAL ABOVE FRONT DOORS TRIM.	
	CLEAN EXTERIOR FRONT DOOR TRIM,	
	SILL BELOW DOOR RIGHT SIDE SAW CUT.	
GARAGE DOORS	ADJUST GARAGE DOOR HARD TO UNLOCK.	

A REFERENCE FOR FUTURE WARR	ANTY REQUESTS. designate someone to conduct the PDI in the	E HOME'S CONDITION BEFORE THE PURCHASE neir place should ensure they provide written authors.	
I have inspected my new home and I	agree that the description of the items listed	on this form are accurate.	
	\$ ~ \$		
??????	-	Sumit Chauhan	
Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature
		Gisella Fiore	H
Designate's Name (print)	Designate's Signature	Inspector's Name (print)	Inspector's Signature
Date (YYYY/MM/DD)	2023/10/27	October 27, 2023	