Enrollment:

Purchaser Name: Octavia L WILLIAMS

Phone Res: (416) 568-3561 Phone Bus: (647) 293-1821 Closing Date: November 31, 2023 Inspector: Alexandria Damianidis HOMES

Vendor / Builder:

Project: Zancor Oakville Ltd.

Lot / Phase: 231 / 1

Plan:

Address: 2450 Old Bronte Road, Suite 231

Municiaplity:

Inspection Date: November 06, 2023

Page 1 of 2 Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

KITCHEN		
CABINETS	CHIP AT UPPER CABINET RIGHT OF SINK AT CORNER	
	CHIP AT UPPER CABINET LEFT OF SINK AT BOTH CORNERS	
	CHIP AT UPPER CABINET ABOVE MICROWAVE	
	CHIP AT UPPER CABINET LEFT OF MICROWAVE	
	CHIPS AT FILLER PIECE RIGHT OF FRIDGE AND AT BANK OF DRAWERS LEFT SIDE - ALL THE WAY DOWN	
	CHIP AT UPPER CABINET ABOVE FRIDGE	
	CHIP ON FRIDGE CABINET TOP RIGHT CORNER	
	CHIP AT 1ST AND 4TH BANK OF DRAWER	
	PAINT ON CABINET BELOW SINK	
	CHIP ON CABINET RIGHT OF SINK	
	SHELF MISSING AT UPPER CABINET RIGHT OF MICROWAVE - AND HO UNHAPPY WITH BOX INSIDE CABINETS -CAN THIS BE REMOVED??	
WINDOWS	SLIDING DOOR TRIM DAMAGED AND SLIDING DOOR NOT LOCKING - ADJUST DOOR	
BEDROOM #2		
ELECTRICAL/LIGHTING	CAT 6 NOT COMPLETE	
POWDER ROOM		
NOTE:	BOTTOM GABLE TRIM PIECE NOT FLUSH	
	BACK GABLE HAS LOTS OF EXTRA CUT OUTS	
FLOORING	T MOLD NOT FLUSH, GAPPING IN BETWEEN. MOVES WHEN YOU STEP ON IT	
FOYER/HALL		
NOTE:	REMOVE PAINT FROM LIGHT SWITCHES, OUTLETS, HINGES AND DOOR HANDLES THROUGHOUT	
FLOORING	REMOVE PAINT FROM HARDWOOD PLANK AT FOYER	

Enrollment:

Purchaser Name: Octavia L WILLIAMS

Phone Res: (416) 568-3561
Phone Bus: (647) 293-1821
Closing Date: November 31, 2023
Inspector: Alexandria Damianidis



Vendor / Builder:

Project: Zancor Oakville Ltd.

Lot / Phase: 231 / 1 Plan:

Address: 2450 Old Bronte Road, Suite 231

Municiaplity:

Inspection Date: November 06, 2023

Page 2 of 2

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS. * Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.						
I have inspected my new home and I agree that the description of the items listed on this form are accurate.						
Octavia L WILLIAMS	0,100					
Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature			
		Alexandria Damianidis	AD .			
Designate's Name (print)	Designate's Signature	Inspector's Name (print)	Inspector's Signature			
Date (YYYY/MM/DD)	2023/11/06	November 06, 2023				