Enrollment:

Purchaser Name: ?????

Hodan, A Hassan

Phone Res:

Phone Bus: (647) 488-5883 **Closing Date:** November 28, 2023

Inspector: Gisella Fiore

ZANCOR HOMES PDI Vendor / Builder: 44528

Project: Zancor Homes (Innisfil) Ltd.

Lot / Phase: 247W / 3

Plan:

Address: 1639 Luno Way

Municiaplity:

Inspection Date: November 20, 2023

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

Page 1 of 2

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- · Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- · Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- · Windows, interior and exterior doors. Door locks
- · Faucets: Kitchen, bathroom, laundry room
- · Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- · Heat Recovery Ventilation system, if provided
- Heating system
- Hot water heater, if provided (not rental)
- · Air conditioning system, if provided and if conditions permit

l	KITCHEN			
	CABINETS	CHIP AT BOTTOM MICROWAVE GABLE ABOVE DRAWER AND RIGHT OF DRAWER AT FRIDGE GABLE		
		FILL CROWN MOULDING AT CEILING THROUGHOUT AT SEAMS.		
		DENT ON ISLAND GABLE FACING DW		
	RANGEHOOD	HOODFAN NOT WORKING. ONLY LIGHT.		
	WINDOWS	DENT ON RIGHT MULIN		
	FOYER/HALL			
	FLOORING	VINYL SHORT LEFT OF STRINGER		
		SECURE T MOLD NOT GLUED DOWN AT FRONT DOOR/ LIVING ROOM MOVING		
		AND PANTRY.		
	STAIRS	DAMAGED STRINGER BELOW NOSING AT STAIRS TO BASEMENT		
	WINDOWS	ADJUST MAN DOOR		
	MASTER ENSUITE BATI	4		
	VANITY CABINETS	REMOVE DIRT OFF CABINET BELOW		
	FLOORING	ADJUST CARPET SHIM		
	SHARED ENSUITE			
	MIRROR	CHIP AT LEFT SIDE MIRROR		
	LAUNDRY ROOM			
	WINDOWS	CLEAN LEFT FIXED GLASS.		
	BEDROOM 4 ENSUITE			
	VANITY CABINETS	DAMAGED COUNTERTOP LEFT SIDE AT LIP.		
	EXTERIOR			
	NOTE:	REMOVED NAILS OFF FLAT ROOF.		
		INSPECT FLASHING AT ROOF ABOVE GARAGE AT BRICK- HOMEOWNER		
		REQUESTING TO BE SECURED		
		CUPPED SHINGLE RIGHT SIDE AT ROOF ABOVE GARAGE		

Enrollment:

Purchaser Name: ?????

Hodan, A Hassan

Phone Res:

Phone Bus: (647) 488-5883

Closing Date: November 28, 2023

Inspector: Gisella Fiore

ZANCOR

Page 2 of 2

Vendor / Builder: 44528

Project: Zancor Homes (Innisfil) Ltd.

Lot / Phase: 247W / 3

Plan:

Address: 1639 Luno Way

Municiaplity:

Inspection Date: November 20, 2023

UPPER HALL	
 RAILING	SCRATCH ON X2 RAILING AT CORNER OF UPPER RAILING FACING MASTER
POWDER ROOM	
FLOORING	OVER CUT AT TILE BELOW TOLIET.

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.

I have inspected my new home and I agree that the description of the items listed on this form are accurate.

?????

Hodan, A Hassan

Purchaser's Name (print) Purchaser's Signature

Purchaser's Name (print)

Purchaser's Signature

Gisella Fiore

Designate's Name (print) Designate's Signature

Inspector's Name (print)

Inspector's Signature

Date (YYYY/MM/DD) 2023/11/20

November 20, 2023