



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

8 EDVAC DRIVE, BRAMPTON ON L6S 5P2
TEL (905) 672-1233 FAX (905) 672-1076

WO # W20330

Pack Slip:5521

Service Date: Nov 21, 2023

Priority: Normal Status: SCHEDULED

BUILDER

Customer: 8030030 City: OAKVILLE Received: Nov 08, 2023
Name: ZANCOR THE BRANCH CONDOS Service Phone(s):
Service Fax: Site Phone: (416) 566-2066 Time:
Site Fax: Lot#: 2ND FLOOR Order: H801163-1
Phase: 243

RESIDENT INFORMATION

Home Owner Name: TETYANA MARUSHKEVYCH Address:
Home Phone(s): Work Phone(s):
Cell Phone(s): 905-399-5035 Email(s): TMARUSHKEVYCH@HOTMAIL.COM

LINKED ORDER INFORMATION (H801163-1)

Customer: 8030030 ZANCOR THE BRANCH CONDOS House Model: 2ND FLOOR
Lot #: 2ND FLOOR Phase: Elevation:

SERVICE INSTRUCTIONS

CLOSING ON NOVEMBER 16TH 2023

INVESTIGATE AND CORRECT

DAI #166836 - PDI - FOYER/HALL - WINDOWS - MULLIN CRACKED LEFT BOTTOM CORNER OF FIXED WINDOW - NEED A53

DAI #166837 - PDI - FOYER/HALL - CLOSET - COMMUNICATION PANEL TO BE ADJUSTED - NOT CLOSING PROPERLY - NOT NEWMAR

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
10	53 - ADAPTOR PART 2 REQUIRE PROFILE #53 IN WHITE @ 120" LONG	TBA	OTHER - REPLACEMENT PARTS	120	BONE WHITE UC113812	1

Problem Description:

DONE

☐ Warranty

Material \$

Labour \$

☐ CHARGEABLES

Material \$

Labour \$

P.O.#:

Cause:

Solution:

Date Completed:

Approved:

Time:

Service Signature:

KHEM