



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

8 EDVAC DRIVE, BRAMPTON ON L6S 5P2
TEL (905) 672-1233 FAX (905) 672-1076

WO # W20406

Pack Slip:5698

Service Date: Nov 17, 2023

Priority: Normal Status: SCHEDULED

BUILDER

Customer: 8030030 City: OAKVILLE Received: Nov 13, 2023
Name: ZANCOR THE BRANCH CONDOS Service Phone(s): Time:
Service Fax: Site Phone: (416) 566-2066 Order: H801165-1
Site Fax: Lot#: 4TH FLOOR Phase: 412

RESIDENT INFORMATION

Home Owner Name: DAMIAN FETZ Address:
Home Phone(s): Work Phone(s):
Cell Phone(s): 289-969-7888 Email(s): DAMIAN.FETZ@GMAIL.COM,
BECKIEFETZ@GMAIL.COM

LINKED ORDER INFORMATION (H801165-1)

Customer: 8030030 ZANCOR THE BRANCH CONDOS House Model: 4TH FLOOR
Lot #: 4TH FLOOR Phase: Elevation:

SERVICE INSTRUCTIONS

INVESTIGATE AND CORRECT

DAI#163046- PDI- FOYER/ HALL- WINDOWS SCRATCH DAMAGE ON SLIDING DOOR TRIM

DAI# 167335- INTERVAL- BEDROOM 2 BOTTOM OF THE WINDOWS NEEDS TO BE FIXED

DAI #167253 - INTERVAL - BEDROOM 2 - GENERAL - TOP RIGHT CORNER AND RIGHT CORNER OF BEDROOM WINDOW NEEDS TOUCH UP

DAI #167255 - INTERVAL - BEDROOM 2 - GENERAL - WINDOW FRAME IN BEDROOM NEEDS TOUCH UP

Problem Description: Complete

☐ Warranty ☐ CHARGEABLES
Material \$ _____ Material \$ _____
Labour \$ _____ Labour \$ _____
P.O.#: _____

Cause: _____

Solution: _____

Date Completed: _____ Approved: _____

Time: _____ Service Signature: _____
KHEM