



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

8 EDVAC DRIVE, BRAMPTON ON L6S 5P2
TEL (905) 672-1233 FAX (905) 672-1076

WO # W20353
Pack Slip:6068

Service Date: Nov 15, 2023

Priority: Normal

BUILDER

Status: SCHEDULED

Customer: 8030030

Name: ZANCOR THE BRANCH CONDOS

Service Fax:

Site Fax:

City: OAKVILLE

Service Phone(s):

Site Phone: (416) 566-2066

Lot#: 8TH FLOOR

Received: Nov 09, 2023

Time:

Order: H801169-1

Phase: 816

RESIDENT INFORMATION

Home Owner Name: EN WEI

Home Phone(s):

Cell Phone(s): 647-299-6169

Address:

Work Phone(s):

Email(s): ENWEI8899@GMAIL.COM

LINKED ORDER INFORMATION (H801169-1)

Customer: 8030030 ZANCOR THE BRANCH CONDOS

Lot #: 8TH FLOOR

Phase:

House Model: 8TH FLOOR

Elevation:

SERVICE INSTRUCTIONS

INVESTIGATE AND CORRECT

DAI #166966 - PDI - LIVING ROOM - WINDOWS - DAMAGED MULIN ABOVE OPERATING WINDOW

Problem Description: No Access Under Appointment. Complete

☐ Warranty

Material \$ _____

Labour \$ _____

☐ CHARGEABLES

Material \$ _____

Labour \$ _____

P.O.#: _____

Cause: _____

Solution: _____

Date Completed: _____

Approved: _____

Time: _____

Service Signature: _____

KHEM