Enrollment:

Purchaser Name: Manpreet Kaur Pooni

Phone Res:

Phone Bus: (514) 808-5704 Closing Date: November 27, 2023 Inspector: Alexandria Damianidis HOMES

Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: 80B / 1B

Plan:

Address: 26 Gatherwood Terrace

Municiaplity:

Inspection Date: November 24, 2023

Page 1 of 2 Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

## DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

## **OPERATING CONDITION**

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

MACTED ENGLISTE DATIL		
MASTER ENSUITE BATH		
FAUCETS/PLUMBING	UPGRADED BATH ACCESSORIES NOT SUPPLIED THROUGHOUT - SITE TO INSTAL BASED ON	 
	PHOTOS	
NOTE:	TOUCH UP BASEBOARDS THROUGHOUT HOME, GAPS	 
KITCHEN		
CABINETS	ADJUST CABINETS THROUGHOUT	 
	STOPPER MISSING BELOW SINK	 
FLOORING	GROUT MISSING AT SLIDING DOOR	 
ELECTRICAL/LIGHTING	FLIP KITCHEN LIGHT, TO SAME AS LIVING ROOM	 
SINK/FAUCET/PLUMBING	SOAP DISPENSER NOT INSTALLED AT SINK	 
FOYER/HALL		
FRONT DOORS	TRIM MISSING AT FRONT DOOR	 
	CHIPS AT ASTRICAL AT FRONT DOOR	 
FLOORING	TILE CUT SHORT IN CLOSET	 
TRIM	TRIM PIECE MISSING BELOW FRONT DOOR	 
NOTE:	REMOVE PAINT ON FRONT DOOR TRIM	 
LAUNDRY ROOM		
CABINETS	ADJUST RIGHT SHELF SLANTED	 
SHARED ENSUITE		
COUNTERTOPS	SIDE SPLASHES SHARP BOTH SIDES	 
BEDROOM #2		
NOTE:	ADJUST DOORS THROUGHOUT	 
BEDROOM #3		
NOTE:	ADJUST PATIO DOOR	 

Enrollment:

FAMILY ROOM

WALLS

Purchaser Name: Manpreet Kaur Pooni

Phone Res: Phone Bus: (514) 808-5704

Closing Date: November 27, 2023

NAIL POP AT STIPPLE

ZANCOR

Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: 80B / 1B

Plan:

Address: 26 Gatherwood Terrace

Municiaplity:

Inspection Date: November 24, 2023

Inspector: Alexandria Damianidis Page 2 of 2 LIVING ROOM ELECTRICAL/LIGHTING CONFIRM IF LIGHT IS REQUIRED IN LIVING AREA, ROUGH IN ONLY EXTERIOR GARAGE DOORS ADJUST WEATHERSTRIP ON LEFT GARAGE DOOR DENTS ON GARAGE MAN DOOR NOTE:

A REFERENCE FOR FUTURE WAR	RANTY REQUESTS. to designate someone to conduct the PDI in th	E HOME'S CONDITION BEFORE THE PURCHAS neir place should ensure they provide written auth	
I have inspected my new home and	I agree that the description of the items listed	on this form are accurate.	
Manpreet Kaur Pooni	INC		
Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature
			4
		Alexandria Damianidis	
Designate's Name (print)	Designate's Signature	Inspector's Name (print)	Inspector's Signature
Date (YYYY/MM/DD)	2023/11/24	November 24, 2023	