Enrollment:

Purchaser Name: Hhd Zid Haffer

Phone Res:

Phone Bus: (647) 472-9143 **Closing Date:** November 30, 2023

ZANCOR HOMES PDI Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: 93B / 1B

Plan:

Address: 17 Gatherwood Terrace

Municiaplity:

Inspection Date: November 27, 2023

Inspector: Alexandria Damianidis Page 1 of 3

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

EXTERIOR		•	•	
NOTE:	MISSING COLD CELLAR ROOM VENTS			
	RE PAINT FRONT DOOR LOTS OF SCRATCHES.			
	REMOVE PAINT OFF /SCRATCHES AT FRONT DOOR TRIM AND ASTRICAL			_
BASEMENT				
NOTE:	MISSING MIRROR IN BASEMENT.			
	RAISE BEDROOM DOOR CANNOT CLOSE DUE TO CARPET			_
	MISSING WIRED SHELVING INSIDE CLOSET.			_
	REMOVE MARKER MARKS ON COUNTERTOP AT SINK.			_
WINDOWS	SLOPPY WORKMANSHIP AT BASEMENT WINDOWS TO BE CAULKED SANDED PAINTED.			_
	ADJUST COLD CELLAR ROOM DOOR NOT CLOSING			_
STAIRS	DAMAGE POST RIGHT OF 5/6 TREAD AT STAIRS FROM BASEMENT TO MAIN FLOOR.		- 	_
KITCHEN				
CABINETS	CHIP AT BOTTOM GABLE AT FLOOR LINE FACING BREAKFAST			
	DAMAGED KICKPLATE RIGHT OF STOVE.			_
	CHIP AT UPPER RIGHT CABINET LEFT OF HOODFAN			_
	CHIP AT DRAWER BELOW MICROWAVE.			_
	SCRATCH ON UPPER RIGHT CABINET LEFT OF FRIDGE.			_
	CHIP AT LEFT GABLE LEFT OF DW			_
NOTE:	BACKSPLASH NOT INSTALLED AT RIGHT AND LEFT OF FRIDGE			_
FLOORING	REMOVE OVERSPRAY AT TILE BY STOVE			_
	INSPECT RIGHT OPERATING WINDOW LEFT OF SLIDING DOOR FOR CRACK AT TOP LEFT MULIN			_
	OR GLUE.			
POWDER ROOM				
FLOORING	CHIPPED TILE AT T MOLD AT ENTRANCE TO POWER ROOM. AND METAL T MOLD SLANTED.	·	·	

Enrollment:

Phone Res:

Purchaser Name: Hhd Zid Haffer

ZANCOR HOMES PDI

Page 2 of 3

Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: 93B / 1B

Plan:

Address: 17 Gatherwood Terrace

Municiaplity:

Inspection Date: November 27, 2023

Phone Bus: (647) 472-9143

Closing Date: November 30, 2023

Inspector: Alexandria Damianidis

POWDER ROOM			
NOTE:	CHIP AT LEFT CABINET LEFT OF SINK AND GABLE AT FLOOR LINE. AND PAINT ON RIGHT		
	CABINET DOOR.		
WALLS	SEAM. IN DRYWALL AT CEILING FAN		
MASTER ENSUITE BATH			
VANITY CABINETS	CHIP AT BOTTOM LEFT CABINET BELOW RIGHT SINK		
FOYER/HALL			
FLOORING	EXTEND HARDWOOD BELOW TRIM AND STRINGER AT LANDING TO SECOND FLOOR		
WALLS	HOMEOWNER, UNHAPPY WITH DRYWALL FINISHING AT MUDROOM		
STAIRS	STAIRS LEADING TO BASEMENT LANDING SQUEAKING		
	MISSING STAIN AT TRIM AT MUDROOM		
	CRACKED TRIM AT STAIRS TO 2ND FLOOR BEFORE LANDING		
FRONT DOORS	DENT ON ASTRICAL AT FRONT DOOR		
	DENT ON LEFT FIXED DOOR		
	MISSING SCREW CAP BELOW HANDLE.		
	WEATHER STRIP NOT INSTALLED.		
	PAINT SHOEMOLD AT FRONT FOYER AND YELLOW PATCHES INSIDE CLOSET.		
NOTE:	GARAGE LIGHT NOT TURNING ON		
LIBRARY/DEN			
NOTE:	REMOVE PAINT OFF GLASS INSERTS AT DOOR.		
DINING ROOM			
NOTE:	UNABLE TO SECURE HRV VENT- INSPECT FLOORING IF CUT CORRECT		
LAUNDRY ROOM			
NOTE:	ADJUST CLOSET DOOR IN LAUNDRY (BEDROOM) UPSTAIRS HITTING CARPET.		
	ADJUST WINDOW NOT CLOSING		
BEDROOM #4			
WINDOWS	ADJUST WINDOW INSIDE CLOSET AND INSIDE BEDROOM NOT CLOSING		
FLOORING	REMOVE DEBRIS FROM CARPET AT ENTRANCE TO BATHROOM		
WALLS	SLOPPY DRYWALL FINISH RIGHT AND LEFT OF WALL TILE AT TUB.		
SHARED ENSUITE			
FAUCETS/PLUMBING	ADJUST SINK FACUET LEFT SIDE SPRAYING OUT		
BEDROOM #3			
FLOORING	RAISE CARPET AT ENTRANCE TO SHARED AND BEHIND DOOR		
BEDROOM 2 ENSUITE			<u> </u>
COUNTERTOPS	CHIP AT RIGHT AND LEFT COUNTERTOP EDGE.		

Enrollment:

Purchaser Name: Hhd Zid Haffer

Phone Res:

Phone Bus: (647) 472-9143

Closing Date: November 30, 2023

Inspector: Alexandria Damianidis



Page 3 of 3

Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: 93B / 1B

Plan:

Address: 17 Gatherwood Terrace

Municiaplity:

Inspection Date: November 27, 2023

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf. I have inspected my new home and I agree that the description of the items listed on this form are accurate. Hhd Zid Haffer Purchaser's Signature Purchaser's Name (print) Purchaser's Signature Purchaser's Name (print) Alexandria Damianidis Designate's Signature Inspector's Name (print) Inspector's Signature Designate's Name (print) Date (YYYY/MM/DD) 2023/11/27 November 27, 2023