Enrollment:

Purchaser Name: Barinder Vic JHAWAR

Baldip Singh JHAWAR

Phone Res: (647) 280-0030 Phone Bus: (647) 280-0030

Closing Date: December 15, 2023 Inspector: Gisella Fiore

HOMES

Vendor / Builder:

Project: Zancor Oakville Ltd.

Lot / Phase: 352 / 1

Plan:

Address: 2450 Old Bronte Road, Suite 352

Municiaplity:

Inspection Date: November 28, 2023

Page 1 of 2 Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

KITCHEN		
CABINETS	SECURE FREEZER STRIP INSIDE FRIDGE	
	REMOVE BLACK MARK OF RIGHT CABINET BELOW SINK	
	CHIP ON RIGHT BASE CABINET OF SINK	
	REMOVE BLACK MARK OFF LEFT UPPER CABINET TO SINK	
	REMOVE BLACK MARK OF 4TH BANK OF DRAWER	
	REMOVE BLACK MARK OF DISHWASHER PANEL	
FLOORING	CHIP IN 5TH PLANK FROM FOYER CLOSET AT FRONT DOOR	
LIVING ROOM		
WINDOWS	BALCONY SCREEN NOT INSTALLED - ADJUST BALCONY SLIDER	
WALLS	VENT COVER NOT INSTALLED	
LAUNDRY ROOM		
NOTE:	WASHHER & DRYER NOT CONNECTED	
FLOORING	SECURE THRESHOLD - NOT SITTING FLUSH	
MASTER BEDROOM		
WINDOWS	ADJUST WINDOW - NOT LOCKING	
MASTER ENSUITE BATH		
VANITY CABINETS	CHIP INSIDE CABINET AT BOTTOM GABLE	
GENERAL COMMENTS		
-	PAINT TOUCH UP THROUGHOUT	

Enrollment:

Purchaser Name: Barinder Vic JHAWAR

Baldip Singh JHAWAR

Phone Res: (647) 280-0030
Phone Bus: (647) 280-0030
Closing Date: December 15, 2023
Inspector: Gisella Fiore

ZANCOR HOMES Vendor / Builder:

Project: Zancor Oakville Ltd.

Lot / Phase: 352 / 1

Plan:

Address: 2450 Old Bronte Road, Suite 352

Municiaplity:

Inspection Date: November 28, 2023

Page 2 of 2

A REFERENCE FOR FUTURE WARRANT	Y REQUESTS. ignate someone to conduct the PDI in the	HOME'S CONDITION BEFORE THE PURCHASE ir place should ensure they provide written autho				
I have inspected my new home and I agree that the description of the items listed on this form are accurate.						
Barinder Vic JHAWAR	BR	Baldip Singh JHAWAR				
Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature			
		Gisella Fiore	C/L			
Designate's Name (print)	Designate's Signature	Inspector's Name (print)	Inspector's Signature			
Date (YYYY/MM/DD)	2023/11/28	November 28, 2023				