Enrollment:

Purchaser Name: Mary Anna Matti

Bassam Binow Matti

Phone Res:

Phone Bus: (416) 320-2283 Closing Date: December 07, 2023

Inspector: Alexandria Damianidis

HOMES

Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: 133B / 1B

Plan:

Address: 31 Ida Terrace

Municiaplity:

Inspection Date: December 01, 2023

Page 1 of 2 Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

MASTER ENSUITE BATH		
FLOORING	REMOVE GROUT BELOW VANITY MIDDLE	
WALLS	INSPECT CEILING TILE LEFT OF FAUCET	
BEDROOM #2		
TRIM	TRIM BOWED AT RIGHT WALL	
LAUNDRY ROOM		
CABINETS	CUT OUT MISSING FOR PLUMING FOR WASHER	
MAIN BATHROOM		
VANITY CABINETS	BACK PANEL WHERE MEETS BOTTOM GABLE CHIPPED.	
EXTERIOR		
NOTE:	REMOVE STONES OFF FLAT ROOF ABOVE GARAGE	
	CAULKING REQUIRED ABOVE FLASHING AT FLAT ROOF ABOVE GARAGE	
FOYER/HALL		
STAIRS	CHIP AT 4TH TREAD AT STAIRS TO 2ND FLOOR	
	CRACK AT NEWEL POST AT 2ND FLOOR.	
	HOLE IN RAILING AT STAIRS TO 2ND FLOOR	
	CHIP AT OUTSIDE STRINGER AT 3RD TREAD AT STAIRS TO 2ND FLOOR.	
	BUBBLE AT OUTSIDE STRINGER BY 2ND TREAD	
	DENT AT OUTSIDE STRINGER AT STAIRS TO 2ND.	
	CRACK AT 2ND TREAD AT STAIRS TO 2ND FLOOR	
	FILL GAP AT FLOOR LINE BY NEWEL AT MAIN FLOOR	 - <u></u>
	SCRATCH AT 6TH PLANK FROM STAIRS TO BASEMENT.	 - <u></u>
FLOORING	HARDWOOD SHORT BELOW TRIM AT STAIRS TO BASEMENT	
	CHIPPED AT 2ND PLANK BY NOSING AT 2ND FLOOR	

Enrollment:

Purchaser Name: Mary Anna Matti

Bassam Binow Matti

2023/12/01

Phone Res:

Date (YYYY/MM/DD)

Phone Bus: (416) 320-2283

Closing Date: December 07, 2023

Inspector: Alexandria Damianidis

ZANCOR HOMES PDI

Page 2 of 2

Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: 133B / 1B

Plan:

Address: 31 Ida Terrace

Municiaplity:

Inspection Date: December 01, 2023

KITCHEN		
FLOORING	CRACK AT 10TH PLANK FROM ISLAND TO STAIRS	
	RASIED PLANK LEFT OF STOVE AT KICKPLATE	
	CRACK AT 2ND PLANK RIGHT OF STOVE	
CABINETS	SECURE KICK PLATE LEFT OF STOVE CHIPPED	
	RED MARKS AT FLOORLINE AT ISLAND FACING LIVING AREA	
LIVING ROOM		
FLOORING	CHIP AT 8TH PLANK FROM FIXED WINDOW	

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.

I have inspected my new home and I agree that the description of the items listed on this form are accurate.

Mary Anna Matti

Purchaser's Name (print)

Purchaser's Signature

Alexandria Damianidis

Designate's Name (print)

Inspector's Signature

Inspector's Signature

December 01, 2023