



NEWMAR WINDOW MFG. INC.  
ALPA LUMBER GROUP

8 EDVAC DRIVE, BRAMPTON ON L6S 5P2  
TEL (905) 672-1233 FAX (905) 672-1076

WO # W20675  
Pack Slip:5567

Service Date: Nov 29, 2023

Priority: Normal Status: SCHEDULED

BUILDER

Customer: 8030030 City: OAKVILLE Received: Nov 24, 2023  
Name: ZANCOR THE BRANCH CONDOS Service Phone(s):  
Service Fax: Site Phone: (416) 566-2066 Order: H801164-1  
Site Fax: Lot#: 3RD FLOOR Phase: 350

RESIDENT INFORMATION

Home Owner Name: Address:  
Home Phone(s): Work Phone(s):  
Cell Phone(s): Email(s):

LINKED ORDER INFORMATION (H801164-1)

Customer: 8030030 ZANCOR THE BRANCH CONDOS House Model: 3RD FLOOR  
Lot #: 3RD FLOOR Phase: Elevation:

SERVICE INSTRUCTIONS

INVESTIGATE AND CORRECT

DAI #168008 - PDI - MASTER BEDROOM - WINDOWS - CHIP ON WINDOW MULLION AT FLOOR LINE OF FIXED WINDOW +  
CLEAN BLACK MARKS THROUGHOUT *DONE*

DAI #168011 - PDI - LIVING ROOM - WINDOWS - ADJUST BALCONY SLIDER & SCREEN - NOT LOOKING PROPERLY *DONE*

DAI #168012 - PDI - LIVINGROOM - CLEAN UP WINDOW MULLIONS ALONG BALCONY DOOR (BLACK MARKS) *DONE*

Problem Description:

☐ Warranty

Material \$

Labour \$

☐ CHARGEABLES

Material \$

Labour \$

P.O.#:

Cause:

Solution:

Date Completed:

Approved:

Time:

Service Signature:

KHEM