



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

8 EDVAC DRIVE, BRAMPTON ON L6S 5P2
TEL (905) 672-1233 FAX (905) 672-1076

WO # W20674
Pack Slip:5521

Service Date: Nov 29, 2023

Priority: Normal Status: SCHEDULED

BUILDER

Customer:	8030030	City:	OAKVILLE	Received:	Nov 24, 2023
Name:	ZANCOR THE BRANCH CONDOS	Service Phone(s):		Time:	
Service Fax:		Site Phone:	(416) 566-2066	Order:	H801163-1
Site Fax:		Lot#:	2ND FLOOR	Phase:	232

RESIDENT INFORMATION

Home Owner Name:	Address:
Home Phone(s):	Work Phone(s):
Cell Phone(s):	Email(s):

LINKED ORDER INFORMATION (H801163-1)

Customer:	8030030 ZANCOR THE BRANCH CONDOS	House Model:	2ND FLOOR
Lot #:	2ND FLOOR	Phase:	Elevation:

SERVICE INSTRUCTIONS

INVESTIGATE AND CORRECT

DAI #168001 - PDI - MASTER BEDROOM - WINDOWS - DENT ON WINDOW MULLION RIGHT OF OPERATING WINDOW **DONE**

DAI #168002 - PDI - MASTER BEDROOM - WINDOWS - WINDOW SCREEN SCRATCHED TOP LEFT CORNER **DONE**

DAI #168003 - PDI - LIVINGROOM WINDOWS - ADJUST BALCONY SLIDER & DOOR - NOT LOCKING **DONE**

Problem Description: _____

☐ Warranty

Material \$ _____

Labour \$ _____

☐ CHARGEABLES

Material \$ _____

Labour \$ _____

P.O.#: _____

Cause: _____

Solution: _____

Date Completed: _____

Approved: _____

Time: _____

Service Signature: _____

KHEM