


Enrollment: Purchaser Name: Mohammad Jafar YASOUBI Phone Res: Phone Bus: Closing Date: December 19, 2023 Inspector: Gisella Fiore		Vendor / Builder: Project: Zancor Oakville Ltd. Lot / Phase: 438 / 1 Plan: Address: 2450 Old Bronte Road, Suite 438 Municipality: Inspection Date: December 08, 2023
Page 1 of 2		

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

- | | |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| DAMAGED, INCOMPLETE OR MISSING <ul style="list-style-type: none">• Windows, side lights and other glazing. Window and door screens• Bathtub sinks and toilets• Bathroom accessories if provided• Mirrors, counter tops and cabinetry• Flooring (hardwood, vinyl, ceramic tiles, carpeting)• Interior finished and trim carpentry• Furnace• Hot water heater, if provided (not rental)• Exterior finished, driveways, walkways, decks and landscaping | OPERATING CONDITION <ul style="list-style-type: none">• Windows, interior and exterior doors. Door locks• Faucets: Kitchen, bathroom, laundry room• Exhaust fans (kitchen, bathrooms) if provided• Electrical outlets and fixtures• Gas fireplaces, incl. circulation fans, if provided• Heat Recovery Ventilation system, if provided• Heating system• Hot water heater, if provided (not rental)• Air conditioning system, if provided and if conditions permit |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|

KITCHEN			
CABINETS	HANDLE NOT INSTALLED ABOVE FRIDGE & CHIP ON RIGHT CORNER	_____	_____
	CHIP ON UPPER LEFT CABINET ABOVE SINK	_____	_____
FOYER/HALL			
WALLS	ADJUST COMMUNICATION PANEL - NOT CLOSING	_____	_____
LAUNDRY ROOM			
WALLS	OVERCUT AT DRYER VENT AT CEILING	_____	_____

Enrollment:
Purchaser Name: Mohammad Jafar YASOUBI
Phone Res:
Phone Bus:
Closing Date: December 19, 2023
Inspector: Gisella Fiore



Page 2 of 2

Vendor / Builder:
Project: Zancor Oakville Ltd.
Lot / Phase: 438 / 1
Plan:
Address: 2450 Old Bronte Road, Suite 438
Municipality:
Inspection Date: December 08, 2023

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

** Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.*

I have inspected my new home and I agree that the description of the items listed on this form are accurate.

Mohammad Jafar YASOUBI

A handwritten signature in black ink, appearing to be "MJ YASOUBI".

Purchaser's Name (print)

Purchaser's Signature

Purchaser's Name (print)

Purchaser's Signature

Gisella Fiore

A handwritten signature in black ink, appearing to be "GFiore".

Designate's Name (print)

Designate's Signature

Inspector's Name (print)

Inspector's Signature

Date (YYYY/MM/DD)

2023/12/08

December 08, 2023