

Delivery Inspection (PDI) Form

RIVERS EDGE

SITE: MASAGA BEACH

LOT #: 238

ENROLMENT # H


Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any "substitutions" of items referred to in, or to be selected under, the Agreement Purchase and Sale (APS).

PAGE #: 1 of 2

Item #	Room/Location	Description
X ①	MSR ENSUITE	REPLACE LAVINATE @ COUNTER RIGHT OF RIGHT SINK - NEW IMAGE
X ②	UPPER HALL	STRETCH CARPET @ MSR BED THROUGHOUT - (35)
③	LANDRY	COMPLETE TRIM TILES TO RIGHT OF ENTRY DOOR. A HARDWOOD LAM @ NOSINK @ MIRROR (OUTSIDE MSR BED) - FCH
X ④	UPPER HALL	
③	KITCHEN	ADJUST ALL DOORS - NEW IMAGE
⑤	KITCHEN	INSTAL Island Plug. - MCKEN (DANE DO NOT SEND NO.)
X ⑦	EXTERIOR	LEFT GARAGE DOOR FRAME DAMAGED @ LAURE RIGHT SIDE - 2 MSR
X ⑧	EXTERIOR	FULL GAR @ LEFT SIDE OF LEFT GARAGE FRAME - MED
		6 INTERIOR
		2 EXTERIOR

All fill top of added trim tiles.

Homeowner Signature:



The Homeowner acknowledges and accepts that all initiated work has been completed in a workman like manner to their satisfaction.

Purchaser's signature

Date (YYYY/MM/DD) 2023 11, 27