Enrollment:

Purchaser Name: Christopher DI GENOVA

Phone Res: (416) 706-4638

Phone Bus:

Closing Date: December 18, 2023

Inspector: Gisella Fiore Page 1 of 2

HOMES

Vendor / Builder:

Project: Zancor Oakville Ltd.

Lot / Phase: 647 / 1

Plan:

Address: 2450 Old Bronte Road, Suite 647

Municiaplity:

Inspection Date: December 12, 2023

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

KITCHEN		
SINK/FAUCET/PLUMBING	FAUCET NOT INSTALLED AT SINK	
	DW NOT CONNECTED.	
CABINETS	CHIP AT LOWER LEFT AND RIGHT CABINET BELOW SINK	
	KICKPLATES NOT INSTALLED	
	REMOVE MARKER AT UPPER RIGHT GABLE RIGHT OF MICROWAVE AND CABINET DOOR DAMAGED AT EDGE	
	MISSING FILLER GABLES, RIGHT AND LEFT SIDE OF MICROWAVE	
	CHIP ON FRIDGE GABLE FRIDGE DOOR AND FREEZER DOOR AND CABINET ABOVE THE FRIDGE.	
	FRIDGE AND FREEZER GABLES NOT INSTALLED.	
FOYER/HALL		
NOTE:	WASHER AND DRYER NOT INSTALLED	
MAIN BATHROOM		
VANITY CABINETS	CHECK AT LEFT GABLE AT FLOOR LINE	
LAUNDRY ROOM		
SINK/FAUCET/PLUMBING	WATER SHUT OFF COVER INSIDE LAUNDRY NOT INSTALLED	
LIVING ROOM		
WINDOWS	MULIN SHORT AT UPPER RIGHT CORNER	

Enrollment:

Purchaser Name: Christopher DI GENOVA

Phone Res: (416) 706-4638

Phone Bus:

Closing Date: December 18, 2023

Inspector: Gisella Fiore

ZANCOR

Vendor / Builder:

Project: Zancor Oakville Ltd.

Lot / Phase: 647 / 1

Plan:

Address: 2450 Old Bronte Road, Suite 647

Municiaplity:

Page 2 of 2 Inspection Date: December 12, 2023

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.

I have inspected my new home and I agree that the description of the items listed on this form are accurate.

Christopher DI GENOVA

Purchaser's Name (print) Purchaser's Signature

Hall Gisel

Gisella Fiore

Designate's Name (print)

Designate's Signature

Inspector's Name (print)

Purchaser's Name (print)

Inspector's Signature

Purchaser's Signature

Date (YYYY/MM/DD) 2023/12/12

December 12, 2023