



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

8 EDVAC DRIVE, BRAMPTON ON L6S 5P2
TEL (905) 672-1233 FAX (905) 672-1076

WO # W20682
Pack Slip:5521

Service Date: Dec 08, 2023

Priority: Normal

Status: SCHEDULED

BUILDER

Customer: 8030030
Name: ZANCOR THE BRANCH CONDOS
Service Fax:
Site Fax:

City: OAKVILLE
Service Phone(s):
Site Phone: (416) 566-2066
Lot#: 2ND FLOOR

Received: Nov 27, 2023
Time:
Order: H801163-1
Phase: 244

RESIDENT INFORMATION

Home Owner Name:
Home Phone(s):
Cell Phone(s):

Address:
Work Phone(s):
Email(s):

LINKED ORDER INFORMATION (H801163-1)

Customer: 8030030 ZANCOR THE BRANCH CONDOS
Lot #: 2ND FLOOR
House Model: 2ND FLOOR
Phase:
Elevation:

SERVICE INSTRUCTIONS

INVESTIGATE AND CORRECT

DAI #168115 - PDI - MASTER BEDROOM - WINDOWS - ADJUST WINDOW - GETTING STUCK WHEN OPENING & CLOSING

DAI #168113 - PDI - BEDROOM 2 - WINDOW MULLION TRIM CUT TO SHORT AT TOP RIGHT BOTTOM RIGHT OF FIXED WINDOW - NOT NEWMAR ISSUE

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
10	84 - BEAUTY CAP 4 REQUIRE PROFILE #84 IN WHITE @ 105" LONG	BEDROOM 2	OTHER - REPLACEMENT PARTS	105	BONE WHITE UC113812	1

Problem Description:

☐ Warranty

Material \$

Labour \$

☐ CHARGEABLES

Material \$

Labour \$

P.O.#:

Cause:

Solution:

Date Completed:

Approved:

Time:

Service Signature: BENNY